



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22002508/Gty3n2 Date: 22/03/2022 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.		SHD 6335D	Veh. Inspected JSN 7092	
Policy No.			Coverage (\$) 0.00	
Claim No.		TAX/03/22/2031	Excess (\$) 0.00	
Assign From		HUA YEN	Assign Date 17/03/2022	
2. Vehicle Particulars & Condition				
Make & Model		YAMAHA Y15ZR	c.c 150	
Engine No.		HIDDEN	Year of Reg. 2018	
Chassis No.		PMYUG0510J0129230	Colour BLUE	
Odometer		-	Steering IN ORDER	
Brakes		IN ORDER	Modification NIL	
General		GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90 R17	MAXXIS	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	110/70-17	METZELER	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.			
5. General Information				
	Accident Date	10/03/2022	Inspect Date / Time	18/03/2022 (02:30 PM)
	Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/SMR22002508/Gty3n2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.