

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002512/ETY3E2

Date: 31/05/2022

REFERENCE

Insured/Claimant: AAK LOGISTICS SERVICES PTE. LTD. Policy No: DMCVSNW00136852101
Date of Loss: 16/03/2022 Nature of Claim: OD Claim No: SNM22D201844/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD9902H**
Make & Model: IVECO STRALIS, 10.3 D AT440S46T/P EURO V 60T (A) Engine No: F3AE3681YU022182919
Reg. Date: 14/11/2014 (Man. Year: 2013) Chassis No: WJMM1VTH4DC264296
Colour: White Odometer: 0 km
Engine Capacity: 7790 cc
Market Value/New Car Price: S\$40,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5
Front Left Side: MAX WIND 4 mm Rear Left Side: MAX WIND 4 mm
Front Right Side: MAX WIND 4 mm Rear Right Side: MAX WIND 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,000.00	36,000.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,000.00	36,000.00	0.00	0.00
- Excess (S\$)	0.00	3,000.00	-3,000.00	
(S\$)	36,000.00	33,000.00	3,000.00	8.33
+ GST 7.00/0.00% (S\$)	2,520.00	0.00	2,520.00	100.00
Nett Amount (S\$)	38,520.00	33,000.00	5,520.00	14.33

INSPECTION

Date of Assignment: 17/03/2022 Present Location: Goldbell Engineering Pte Ltd (Tuas)
Date Inspected: 18/03/2022 Inspected At: Goldbell Engineering Pte Ltd (Tuas)
10 Tuas Ave 18
Singapore 638894
Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$40,000.00
OMV :	\$102,808.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$24,697.00
COE Rebate (2) :	\$6,562.00
Total Rebate (1) + (2) = :	\$6,562.00

The total amount incurred will be Market Value \$40,000.00 minus Total Rebate \$6,562.00 = \$33,438.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Reference		
Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	IVECO STRALIS 10.3 D AT440S46T/P EURO V 60T (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9902H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Repair Cost		45,000.00 F	*45,000.00 F
F=Franchise part.						
			Sub Total (\$)		45,000.00	45,000.00
			- Add. Disc. on L,N Items 20.00/20.00% (\$)		9,000.00	9,000.00
			Total Parts (\$)		36,000.00	36,000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >