

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE001595 Accident Date : 18/12/2021

Vehicle No : GBJ-3418-H Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	TAILGATE / DO	1,998.30	1816/-
1	TAILGATE WINDSCREEN SEAL / ncc	141.20	50/-
1	TAILGATE LOCK X nn	262.30	
1	TAILGATE RUBBER X nn	173.20	
1	TAIL LAMP RH X nn	311.50	
1	REAR BUMPER X nn	632.70	
10	REAR BUMPER CLIPS X nn	50.00	
1	REAR BUMPER SIDE BRACKET RH X nn	17.50	
1	REAR BUMPER STOPPER RH X nn	35.40	

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE001595

Accident Date : 18/12/2021

Vehicle No : GBJ-3418-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER REINFORCEMENT <i>x nn</i>	244.30	
1	REAR END PANEL (OUTER) <i>x nn</i>	247.10	
1	REAR END PANEL (INNER) <i>x nn</i>		
	RESTORE		
	Sub Total	4113.50	
	Discount 10% On Parts	(411.35)	
	<u>Special Nett Item</u>		
1	WINDSCREEN SEALANT <i>/ mc</i>	40.00	
1	REVERSE SENSOR <i>x nn</i>	200.00	
1	END PANEL SEALANT <i>x nn</i>	40.00	
1	LTA STICKER (70 KM/H) <i>/ mc</i>	10.00	

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D21MTHCVE001595
Vehicle No : GBJ-3418-H
Accident Date : 18/12/2021
Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)
Excess : 0.00
Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	LTA STICKER 8 PAX	10.00	
	Sub Total	300.00	60
Labour & Misc			
	LABOUR TO CARRY OUT REAR REPAIR	800.00	290
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	200
	SPRAY RUST PROOF ON AFFECTED AREA	50.00	30
	TO REMOVE & INSTALL ALL TAILGATE FITTING	100.00	50
	TO REMOVE & INSTALL REAR TAILGATE GLASS	150.00	110
			635
			= 2374.40

Steve (CLKK)
18/3/22, 1.00pm

WL PL
3 L/S
L/S
hy PL R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) to be carried out
- Supplementary details must be submitted and is subject to final approval from Insurer/Insurance Company

Acknowledged by Repairer
Signature:
Date: