



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date:

17/3/22

Vehicle:

SMR3734Y

Make / Model:

TOYOTA PRIUS

INSURANCE

LONPAC

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT DOOR RH bt	1	1,359	1258 1,359
2	REAR DOOR RH bt	1	1,359	1201 1,359
3	SIDE SKIRTING LH X NN	1	898	898
	TOTAL PART			2459 3,616
	LIST DOWN	25%		904
	AFTER LIST DOWN			1844.25 2,712
	SPEICAL NETT			
1	FRONT DOOR INNER TRIM CLIP na	1	50	30 50
2	FRONT DOOR CHROME PROTECTOR RH na	1	200	50 200
3	REAR DOOR INNER TRIM CLIP na	1	50	30 50
4	REAR DOOR CHROME PROTECTOR RH na	1	200	50 200
	TOTAL AMOUNT			500
	LABOUR			160
1	CHECK WIRING NN		100	X 100
2	R+R FRONT DOOR GLASS NN		200	X 200
3	R+R FRONT AND REAR DOOR MECHANISM NN		300	X 300
4	KNOCK		800	500 800
5	SPRAY		800	600 800
	TOTAL AMOUNT			1100 2,200
Parts Replacement Amount				1100 3,100
Total Amount for Labour				2,200
Total Amount				5,300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
4p 900100 68
5 days
18/03/22 @ 1450
Resur after repair

1844.25

160.00

1100.00

3104.25

20%

2483.40

4/5 - 2,450