



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22002532/Avy3m4	
			Date: 10/10/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SBS 3397L	Veh. Inspected	SGW 7449P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22000802MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN	Assign Date	18/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMF16307S218349	Colour	BLACK	
Odometer	176551 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/03/2022	Inspection Date	18/03/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	