

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01, #04-02 &**  
**#07-03, Sin Ming Autocity**  
**575722**

**Insurer Reference: TP-GW 4766T**  
**Repairer Reference: 72528**  
**Date calculated: 07/04/2022 1:55 PM**

**Full Report**  
**Registration: SMA 5282K**  
**Printed: 07/04/2022 1:55 PM**

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GW 4766T	Date of Incident:	15/03/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer:	HYUNDAI
Model:	ACCENT (RB)
Sub Model:	BASE MODEL
Model Sheet Number:	30 29 01
Registration:	SMA 5282K
VIN number:	
Odometer:	53148

### Model Specs

FROM 07.2013	AIR CONDITIONING	FOG LAMPS	REAR PARKING SYSTEM
CVT AUTO GEARBOX	TYRES 175/70 HR 14	4-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE			

## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: BOTH OUTER REARLAMPS AND REQUIRED TRIMS ASSEMBLE ATTACHED PARTS RENEW IF NECESS NOT INCLUDED: BUMPER REINFORCEMENT REMOVE AND REFIT		7.0	29.40
95704R00)	R + R REAR PARKING SYSTEM SENSOR/S		5.0	21.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>1.20</b>	<b>12.0</b>	<b>50.40</b>
<b>Total of Labour</b>				<b>50.40</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER COVER NEW PART PAINT K1R		13.0	
	L/R INN PARKING SENS SURFACE PAINT PLAST.		3.0	
	R/R INN PARKING SENS SURFACE PAINT PLAST.		3.0	
	L/R OUT PARKING SENS SURFACE PAINT PLAST.		3.0	
	R/R OUT PARKING SENS SURFACE PAINT PLAST.		3.0	

## Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER COVER NEW PART PAINT K1R	63.96
2681	L/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
2682	R/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
2683	L/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2684	R/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37

### Labour Cost - Paint

		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			25.0	
Preparation Comp. Work Plastic		1.50	15.0	63.00
<b>Total</b>	<b>10 WU/h</b>	<b>4.00</b>	<b>40.0</b>	<b>168.00</b>

### Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	63.96
Surface Painting Plastic	1.48
Material-constant Plastic	28.60
<b>Total</b>	<b>94.04</b>

## Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD
2626	R/R OUT BUMPER BRKT	866141R000	Original	30.00
2583	REAR BUMPER COVER	866501R000	Original	280.00
f: OEM Parts	<b>Savings</b>			<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>			<b>310.00</b>
u: Used parts	<b>Fixed Sundry Parts Price</b>			<b>100.00</b>
	<b>Total</b>			<b>410.00</b>

## Final Calculation

	SGD	SGD
<b>Parts</b>	310.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>410.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 12.0 WU X 42.00 SGD/h	50.40	
<b>Total of Labour</b>		<b>50.40</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 40.0 WU X 42.00 SGD/h	168.00	
Material Cost	94.04	
<b>Total Paint Including Material</b>		<b>262.04</b>
<b>Repair Cost Excludes GST</b>		<b>722.44</b>
GST (+7.0%)		<b>50.57</b>
<b>Repair Cost Included GST</b>		<b>773.01</b>

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.