



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22002544/Kty3s2 Date: 21/04/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLN 9294T
	Policy No.	Z21VP05029195	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025571	Excess (\$)	500.00
	Assign From	GERALD POH WEE BIN	Assign Date	18/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 530i (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBAJA520X0G885162	Colour	METALLIC DARK BLUE
	Odometer	86137 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R19	MICHELIN	7 mm
	L/H Front Tyre	245/40 R19	MICHELIN	7 mm
	R/H Rear Tyre	275/35 R19	MICHELIN	5 mm
	L/H Rear Tyre	275/35 R19	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/03/2022	Inspection Date	21/03/2022
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$138,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	