



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

TO: AIG INSURANCE
AIG Building
78 Shenton Way, Level 1
Singapore 079120


C/O: LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

LETTER OF DEMAND

Tax Invoice : 202209-0126
Date : 06/09/2022
Vehicle : GBA7288L
Make Model : TOYOTA DYNA, 2982cc
Accident Date : 15/03/2022 18:10 (SGT)
Accident Location: LORONG 6 TOA PAYOH, SINGAPORE

Particular	Amount
1. COST OF REPAIR	\$3,400.00
2. LOSS OF USE FOR 03 Days x @\$120.00 per day	\$ 360.00
3. Pre-Repair Inspection for 2 days x @\$120.00 per day	\$ 240.00
4. GIA/LTA SEARCH FEE	\$. 7.45

Singapore Dollars: Four Thousand Seven & Cents Forty-Five Only



YSK Auto Workshop

Total S\$: 4,007.45

=====