



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
IP SWEET HEE	Cust No/Name	/IP SWEET HEE
BLK 677 CHOA CHU KANG CRESCENT	Reg No/Reg Date	SMD2213P / 08/08/201
#10-660	Date In/Mileage	/ 0
SINGAPORE 680677	Chassis No	GF7W0402070
Contact No Mobile: 97600230	Engine No	4J11YP9347
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	P02 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	18/03/2022/ 17:09		265 / AndreChow	21722			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT98000								3150.00
RESPRAY ACCIDENT DAMAGED PORTION ON FRONT BUMPER, LH FRONT FENDER,								2475 /
I-5 BOTH LH DOORS, LH REAR FENDER, LH ROCKER PANEL, LH 'B' PILLAR, 5-5 x 450								
LH WING MIRROR 2								1750 /
E PNT88000								2700.00
RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER, BOTH LH FENDERS, BOTH 5 x 350								120 /
LH DOORS, REPAIR 'B' PILLAR. LH ROCKER PANEL								450.00
E PNT88000								120 /
TRANSFER LH FRONT DOOR TRIM, MECHANISM, ELECTRONICS TO NEW DOOR								450.00
E PNT88000								120 /
TRANSFER LH REAR DOOR TRIM, MECHANISM, ELECTRONICS TO NEW DOOR								450.00
E PNT88000								450.00
REMOVE REAR SEATS, FLOOR TRIM TO FACILITATE REPAIRS								450.00
E PNT88000								450.00
REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS								450.00
A 54900099								450.00
RENEW FRONT UNDERCARRIAGE								30.00
A 54900099								120.00
RENEW REAR UNDERCARRIAGE								120.00
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								30.00
A 10028901								30.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								30.00
M SUNDRY								400.00
TRANSFER LHF TYRE TO NEW SPORTS RIM								400.00
M SUNDRY								
TRANSFER LH REAR TYRE TO NEW SPORTS RIM								
M SUNDRY								
SUPPLY LHF TYRE								
M SUNDRY								
SUPPLY LHR TYRE								

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
IP SWEE HEE	Cust No/Name /IP SWEE HEE
BLK 677 CHOA CHU KANG CRESCENT	Reg No/Reg Date SMD2213P / 08/08/201
#10-660	Date In/Mileage / 0
SINGAPORE 680677	Chassis No GF7W0402070
Contact No Mobile: 97600230	Engine No 4J11YP9347
	Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim P02 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	18/03/2022/ 17:09		265 / AndreChow	21722			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								120 240.00
SUPPLY BODY SEALANT								40 160.00
M SUNDRY								20 50.00
SUPPLY ANTI CORROSION								- 120.00
M SUNDRY								- 120.00
SUNDRIES								
M SUNDRY								
SUPPLY RIKE COOL SOLAR FILM FOR LHF DOOR				(Sub agmt)				
M SUNDRY								
SUPPLY RIKE COOL SOLAR FILM FOR LHR DOOR				(Sub agmt)				
M FACE,FR BUMPER					1.00	851.00	00.00	851.00
M MOULDING,FR BUMPER,LH					1.00	116.00	00.00	116.00
M MOULDING,FR WHEEL ARCH,LH					1.00	160.00	00.00	160.00
M MOULDING,RR WHEEL ARCH,LH					1.00	160.00	00.00	160.00
M MOULDING,RR BUMPER,LH					1.00	106.00	00.00	106.00
M INSULATOR,FR FENDER,LH					1.00	60.00	00.00	60.00
M FENDER,FR LH					1.00	622.00	00.00	622.00
M SHIELD,FR WHEELHOUSE,LH					1.00	164.00	00.00	164.00
M SHIELD,RR WHEEL,RR LH					1.00	22.00	00.00	22.00
M PANEL ASSY,FR DOOR,LH					1.00	930.00	00.00	930.00
M MLDG,F/DR WDO BELT LINE,LH					1.00	88.00	00.00	88.00
M HINGE,FR DOOR,LWR RH					1.00	43.00	00.00	43.00
M HINGE,FR DOOR,LWR LH					1.00	43.00	00.00	43.00
M RUNCHANNEL,F/DR WDO GLA,LH					1.00	149.00	00.00	149.00
M W/STRIP,F/DR OPENG,LWR LH					1.00	47.00	00.00	47.00
M W/STRIP,FR DR OPNG,INR LH					1.00	204.00	00.00	204.00
M REGULATOR,FR DOOR WDO,LH					1.00	178.00	00.00	178.00
M MOTOR,F/DR POWER WDO REG,L					1.00	457.00	00.00	457.00
M GASKET,F/DR OUTSIDE HANDLE					1.00	6.00	00.00	6.00
M BASE,F/DR OUTSIDE HDLE,LH					1.00	135.00	00.00	135.00
M LATCH,FR DOOR,LH					1.00	322.00	00.00	322.00
M ROD,F/DR OUTSIDE HANDLE,LH					1.00	12.00	00.00	12.00
M CABLE,FR DOOR INS LOCK,LH					1.00	19.00	00.00	19.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
IP SWEE HEE	Cust No/Name	/IP SWEE HEE
BLK 677 CHOA CHU KANG CRESCENT	Reg No/Reg Date	SMD2213P / 08/08/201
#10-660	Date In/Mileage	/ 0
SINGAPORE 680677	Chassis No	GF7W0402070
Contact No Mobile: 97600230	Engine No	4J11YP9347
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	P02 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	18/03/2022/ 17:09		265 / AndreChow	21722			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M CHECK,FR DOOR					1.00	31.00	00.00	31.00
M MLDG,R/DR WDO BELT LINE,LH					1.00	79.00	00.00	79.00
M W/STRIP,R/DR OPNG,OTR LH					1.00	161.00	00.00	161.00
M W/STRIP,R/DR OPN,LWR OTR L					1.00	33.00	00.00	33.00
M W/STRIP,RR DOOR OPNG,FR LH					1.00	129.00	00.00	129.00
M RUNCHAN,R/DR WDO GLASS,LH					1.00	113.00	00.00	113.00
M PANEL ASSY,RR DOOR,LH					1.00	851.00	00.00	851.00
M GLASS,RR DOOR WINDOW,LH					1.00	263.00	00.00	263.00
M W/STRIP,R/DR OPNG,INR LH					1.00	96.00	00.00	96.00
M HINGE,FR DOOR,LWR LH					1.00	43.00	00.00	43.00
M HINGE,RR DOOR,UPR LH					1.00	43.00	00.00	43.00
M REGULATOR,R/DR WINDOW,LH					1.00	177.00	00.00	177.00
M GASKET,R/DR OUTSIDE HANDLE					1.00	6.00	00.00	6.00
M BASE,R/DR OUTSIDE HDLE,LH					1.00	48.00	00.00	48.00
M CHECK,RR DOOR					1.00	32.00	00.00	32.00
M CABLE,RR DOOR INS LOCK,LH					1.00	19.00	00.00	19.00
M CABLE,RR DOOR INS HANDLE,L					1.00	24.00	00.00	24.00
M ROD,R/DR OUTSIDE HANDLE,LH					1.00	11.00	00.00	11.00
M LATCH,RR DOOR,LH					1.00	321.00	00.00	321.00
M TAPE,FR DOOR SASH,LH					1.00	42.00	00.00	42.00
M TAPE,RR DOOR SASH					1.00	42.00	00.00	42.00
M TAPE,RR DOOR SASH					1.00	42.00	00.00	42.00
M GARNISH,FR DOOR,LH					1.00	190.00	00.00	190.00
M GARNISH,RR DOOR,LH					1.00	164.00	00.00	164.00
M AIR DAM,SIDE,LH					1.00	544.00	00.00	544.00
M MIRROR ASSY,DOOR,LH					1.00	558.00	00.00	558.00
M COVER,DOOR MIRROR,OTR LH					1.00	139.00	00.00	139.00
M WHEEL,SPARE TIRE DISC (FR LH)					1.00	1102.00	00.00	1102.00
M WHEEL,SPARE TIRE DISC (FR LH)					1.00	1102.00	00.00	1102.00
M ARM ASSY,FR SUSP,LWR LH					1.00	325.00	00.00	325.00
M BOLT,FR SUSP LWR ARM					1.00	11.00	00.00	11.00
M BOLT,FR AXLE CROSSMEMBER					1.00	26.00	00.00	26.00
M BOLT,FR AXLE CROSSMEMBER					1.00	10.00	00.00	10.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
IP SWEE HEE	Cust No/Name	/IP SWEE HEE
BLK 677 CHOA CHU KANG CRESCENT #10-660 SINGAPORE 680677	Reg No/Reg Date	SMD2213P / 08/08/201
Contact No Mobile: 97600230	Date In/Mileage	/ 0
	Chassis No	GF7W0402070
	Engine No	4J11YP9347
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	P02 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
CSM00041	Cash	18/03/2022/ 17:09		265 / AndreChow	21722				
Description of Goods / Services									
M	BAR,FR SUSP STABILIZER					1.00	317.00	00.00	317.00
M	STRUT,FR SUSP,LH					1.00	469.00	00.00	469.00
M	INSULATOR,FR SUSP STRUT					1.00	96.00	00.00	96.00
M	BEARING,FR SUSP STRUT					1.00	32.00	00.00	32.00
M	ARM ASSY,RR SUSP,UPR					1.00	109.00	00.00	109.00
M	LINK,RR SUSP ASSIST					1.00	86.00	00.00	86.00
M	ARM ASSY,RR SUSP TRAIL,LH					1.00	501.00	00.00	501.00
M	ARM ASSY,RR SUSP,LWR					1.00	151.00	00.00	151.00
M	SHOCK ABSORBER,RR SUSP					1.00	257.00	00.00	257.00
M	BAR,RR SUSP STABILIZER					1.00	262.00	00.00	262.00
M	SHOCK ABSORBER,RR SUSP					1.00	257.00	00.00	257.00
M	ARM ASSY,RR SUSP,LWR					1.00	151.00	00.00	151.00
M	ARM ASSY,RR SUSP TRAIL,LH					1.00	501.00	00.00	501.00
M	LINK,RR SUSP ASSIST					1.00	86.00	00.00	86.00
M	ARM ASSY,RR SUSP,UPR					1.00	109.00	00.00	109.00
M	INSUL,RR SHOCK ABSORBER					1.00	57.00	00.00	57.00
M	PAD,RR SUSP SPRING,LWR					1.00	19.00	00.00	19.00
M	HUB ASSY,RR WHEEL					1.00	434.00	00.00	434.00
M	GEAR & LINK ASSY,STEERING					1.00	1326.00	00.00	1326.00
M	BEARING,FR WHEEL HUB					1.00	152.00	00.00	152.00
M	HUB ASSY,FR WHEEL					1.00	288.00	00.00	288.00
M	KNUCKLE,LH					1.00	358.00	00.00	358.00
M	PANEL,QTR,OTR LH					1.00	1298.00	00.00	1298.00

SURVEYOR NAME: Steve (LKK) 21/3/22, 11:00am

SURVEYOR SIGNATURE: OD- M-1 AL

DATE: EX-100-?

REMARKS: PIP, M BL 14

Confirm & accepted by

14 days

7% GST on

Nett

29,357.00

2054.99

Total Payable

31,411.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.