

ASS. REC. BY: *Marcus*

REF:

*CS/SMR 22002578/U***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) ___ S + RS ___ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

134H

Vehicle Details

Vehicle No.:

SBE2323E

Vehicle to be Exported:

No

Intended Deregistration Date:

18 Mar 2022

Vehicle Make:

TOYOTA

Vehicle Model:

SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR

Primary Colour:

White

Manufacturing Year:

2016

Engine No.:

2NR8604841

Chassis No.:

NSP1707028324

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$19,369.00

Original Registration Date:

05 Apr 2017

First Registration Date:

05 Apr 2017

Transfer Count:

0

Actual ARF Paid:

\$9,369.00 4684

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

04 Apr 2027

PARF Rebate Amount:

\$7,026.00

Intended COE Rebate Details

COE Expiry Date:

04 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,789.00

COE Rebate Amount:

\$25,628.00

Total Rebate Amount:

\$32,654.00

The information contained herein is correct as at 18 Mar 2022

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2020 Cosmos Blue Audi A3 Cabriolet 1.4TFSI COD.



Stylish Yet Efficient Cabriolet
With Audi's 1.4TFSI COD
Engine & 7 Spd S-tronic
Direct Owner StarAd

PRIME MOTOR & LEASING

SHANGHAI FONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES
 With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Sort by [Date Posted](#) 20 results/page

14 vehicles



sienta

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	sienta		Any	Any	2017	Any	Any	Any	Available
	Toyota	Sienta 1.5A Elegance (OPC)	\$65,800	\$9,810 /yr	20-Dec-2017	1,496 cc	12,000 km	MPV	Available
Convert To Normal Plate Price \$76000 Only! L1 Owner, Super Low Mileage Of Only 12000KM. Fully Maintained And 5 Years Warranty By...									
Posted: 19-Mar-2022									
	Toyota	Sienta 1.5A Standard	\$72,800	\$11,170 /yr	22-Dec-2017	1,496 cc	72,453 km	MPV	Available
Rare Sienta 1.5A (7-Seaters MPV) (Sliding Doors) (Rear Aircon), Best MPV Choice! Called At Borneo Motors With Proof. Genuine Low...									
Lake View Credit Pte Ltd									
Posted: 19-Mar-2022									
	Toyota	Sienta Hybrid 1.5A G	\$69,800	\$12,580 /yr	27-Jul-2017	1,496 cc	-	MPV	Available
Fuel Type: Petrol-Electric									
Full Loan Available! Buy With Confidence! In House Loan Or Bank Loan Available! Fast And Easy Loan Approval! All Our Vehicles Has Und...									
88 Motor Trading									
Posted: 18-Mar-2022									
	Toyota	Sienta Hybrid 1.5A X	\$71,800	\$12,300 /yr	07-Nov-2017	1,496 cc	45,886 km	MPV	Available
Fuel Type: Petrol-Electric									
\$0 Driveaway With Loan Approval Bonus! Free 2yrs Servicing, Low Mileage, Pristine Condition, View It To Believe It, High Loan Available...									
Posted: 17-Mar-2022									
	Toyota	Sienta 1.5A Elegance	\$72,800	\$10,970 /yr	29-Dec-2017	1,496 cc	53,800 km	MPV	Available
Full Servicing Receipt Available, Borneo Motor High Spec Unit With Rear Aircon, Excellent And Well Taken Care, Regularly Serviced And...									
Posted: 16-Mar-2022									
	Toyota	Sienta Hybrid 1.5A X	\$65,800	\$12,670 /yr	20-Mar-2017	1,496 cc	53,216 km	MPV	Available
Fuel Type: Petrol-Electric									
Lowest Priced Sienta Hybrid! OPC Converted. Low Mileage. Excellent Condition. STA/Workshop Inspection Welcome And Encouraged. No...									
Posted: 16-Mar-2022									
	Toyota	Sienta Hybrid 1.5A G	\$74,888	\$12,540 /yr	28-Dec-2017	1,496 cc	50,000 km	MPV	Available
1 Owner Unit. Fresh New Paint. Low Mileage. Very Well Maintained By Previous Owner. Non PHV Unit. 100% Loan/PHV Full Loan Availabl...									
Posted: 13-Mar-2022									
	Toyota	Sienta 1.5A X	\$63,800	\$10,980 /yr	30-Jun-2017	1,496 cc	75,000 km	MPV	Available
1 Owner Unit And Owned By Retiree Owner Using It To Ferry Grandkids And Grocery Shopping Only. Non PHV Unit. Clean Interior And O...									
Tan Wei Auto Pte Ltd									
Posted: 13-Mar-2022									

[Compare](#)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Bik 9004 Tampines Street 93 #01-120 Singapore 528838 Tel. 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 3061/03/22 Your Ref: _____ Date: 18th March 2022
5 days. *Not Allowed* *21/3/22*
4/s *the 2nd After rep.*

MR TAN TECK SIN
 1, Palm Rd, #01-07,
 Singapore 456444

Estimate cost of repair to TOYOTA SIENNA 1.5 (A) MPV - SBE 2323 E

1 pc rear n/s door	<i>body 20</i>	\$ 1,306.60	<i>==</i>
1 pc rear n/s door protector	<i>2.5</i>	125.80	<i>==</i>
1 pc rear n/s door lower garnish	<i>grand</i>	180.20	<i>==</i>
20 pcs rear n/s door inner trim board clips	<i>6</i> @ \$ 4.60	92.00	<i>7</i>
1 pc rear n/s door weatherstrip		718.80	<i>?</i>
1 pc rear n/s door glass regulator		201.90	<i>?</i>
1 pc rear n/s fender	<i>2</i>	1,211.10	<i>X</i>
1 pc rear n/s fender protector	<i>grad</i>	68.80	<i>?</i>
1 pc rear n/s fender inner shield garnish		67.70	<i>?</i>
1 pc rear bumper	<i>cur</i>	482.20	<i>==</i>
10 pcs rear bumper clips	<i>new</i>	48.00	<i>==</i>
1 pc rear bumper n/s side retainer	<i>17</i>	112.20	<i>X</i>
1 pc rear bumper n/s side bracket clips	<i>new</i>	6.80	<i>==</i>
1 pc rear bumper n/s black garnish	<i>grand</i>	122.80	<i>?</i>
1 pc rear bumper n/s wheel guard shield		78.30	<i>?</i>
6 pcs rear bumper n/s wheel guard clips	<i>17</i> @ \$ 4.60	27.60	<i>X</i>
1 pc rear n/s sport rim	<i>cur / 2nd</i>	650.00	<i>X</i>
1 pc rear n/s tyre	<i>src</i>	420.00	<i>X</i>
1 pc rear n/s shock absorber shaft		198.50	<i>?</i>
1 pc rear n/s lower arm (with Axle)		2,633.80	<i>?</i>
1 set rear n/s wheel bearing hub		661.20	<i>?</i>
1 pc rear n/s door lower roller	<i>17</i>	326.80	<i>X</i>
1 pc rear n/s door lower roller bracket	<i>17</i>	103.40	<i>X</i>
		\$ 9,844.50	
Less 25%		\$ 2,461.13	
To wiring check up for affected wiring system.		\$ 7,383.37	
To check & adjust wheel alignment & balancing.		150.00	<i>80</i>
To remove & refix rear n/s door inner trim board cover, glass, regulator, moulding, inner lock, roller & necessary parts.		240.00	<i>80</i>
To remove & refix rear n/s fender inner garnish, carpet, floor mat, garnish & necessary parts.		120.00	<i>80</i>
To remove & refix fuel tank, hose, pipe & necessary parts.		150.00	<i>60</i>
To remove & refix rear n/s fender glass & pump sealant.		<i>17</i> 120.00	<i>X</i>
To remove & refix rear n/s shock absorber shaft, lower arm, wheel bearing hub & necessary parts.		280.00	<i>?</i>
		\$ 8,443.37	
Balance C/F.....			

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3061/03/22 Your Ref: _____ Date: 18th March 2022

MR TAN TECK SIN.,	Balance B/F... \$	8,443.37
To respray coating for affected accident parts.		600.00 SH
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.		1,550.00 600
To respray Tuff-Kote on all affected accident parts.(wheel inner)	120.00	40
To putty & respray (Pearl Colour) on all affected accident parts.	1,650.00	900
To wiring check up for affected wiring system.	50.00	20
To diagnose & re-set rear n/s door auto lock function.	120.00	80
	\$	12,533.37
	=====	

Dollars : Twelve Thousand Five Hundred Thirty Three Dollars And Cents
Thirty Seven Only.

HUP MOTOR TRADING & SERVICE

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: