



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2202744

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 13/05/2022
Reference CS3/III22002592/Tqy3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SKC 6846R

Insured Veh. SMK 8962J

Claim No.

Policy No.

Accident Date 18/02/2022

Inspection Date 24/03/2022

| Description | Total |
|---|---------------|
| Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport) | 120.00 |
| - First Inspection 24.03.2021 01.00pm | |
| - Dismantle Inspection 25.03.2022 03.00pm | |
| - After Repair Inspection 31.03.2022 05.38pm | |
| Merimen Fee | 11.00 |
| Subtotal | 131.00 |
| GST (7%) | 9.17 |
| Grand Total | 140.17 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM