

G

Our Job Ref No : 305509555

Date : 25/03/22

**COMFORTDELGRO  
ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Attn : THEVAN

: SHA2044K

Fax :

19.03.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: LONPAC GBL137C

2. The finalized amount shall be:

- (a) Spare Parts after List discount
- (b) Labour Charges

**Total for Part-By-Part Repair Cost**

- (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less:  
Final Lumpsum Repair cost

\$2,150.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : THEVAN

Date : 25/4/22

**For Official Use Only**

| Item  | Amount        | Document Attached<br>Yes or No | Confirm By<br>(Signature) | Remarks |
|---|---------------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day                                    |               | YES                            |                           |         |
| 2. Loss of Income Paid                                  |               | N                              |                           |         |
| 3. Survey Fees  |               |                                |                           |         |
| 4. LTA Search Fee                                       | \$7.49/\$2.00 | YES                            |                           |         |
| 5. Medical Fees (on behalf<br>of driver, if applicable) |               |                                |                           |         |
| 6. Overrun  |               |                                |                           |         |

Remarks:

# REPAIR ESTIMATE\*

VEHICLE NO SHA2044K

19/03/22

MAKE REG. 15.12.2016

MODEL I-40

CHIANG /LONPAC

| Qty | Parts Description/ Labour   | Type | Unit Price | Amount            |
|-----|-----------------------------|------|------------|-------------------|
| 1   | FRONT BUMPER BRACKET RH     |      |            | \$24.60           |
| 1   | FRONT BUMPER TOP BRACKET RH |      |            | \$22.40           |
| 1   | FRONT BUMPER                |      |            | \$1,052.20        |
| 1   | FRONT BUMPER GRILLE / RH    |      |            | \$93.45           |
| 1   | FRONT FENDER RH             |      |            | \$663.00          |
| 1   | FRONT FENDER SHIELD RH      |      |            | \$174.90          |
| 1   | FRONT WHEEL COVER RH        |      |            | \$217.20          |
| 1   | HEAD LAMP ASSY RH           |      |            | \$1,388.00        |
| 10  | BUMPER CLIPS                |      | \$2.20     | \$22.00           |
|     | <b>SUB TOTAL</b>            |      |            | <b>\$3,657.75</b> |
|     | <b>LESS 20%</b>             |      |            | <b>\$731.55</b>   |
|     |                             |      |            | <b>\$2,926.20</b> |
|     | <b>Labour Charge</b>        |      |            |                   |
|     | Panel Beating               |      |            | \$600.00          |
|     | Spray Painting Charge       |      |            | \$600.00          |
|     | Tuff Kote                   |      |            | \$60.00           |
|     | Check Lighting              |      |            | \$60.00           |
|     | <b>TOTAL LABOUR</b>         |      |            | <b>\$1,320.00</b> |
|     | <b>ESTIMATE TOTAL</b>       |      |            | <b>\$3,862.58</b> |

Thevan  
82235769  
23/3/22 1600  
3days wp  
L/S repair

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: