

Not Withheld

1 day

81484.08

Date: 21/03/2022
Vehicle No: SMX6531P
Model: HYUNDAI AVANTE CN7 1.6
Chassis: KMHLN41ETMU112034
Reg.Year: 2020

Third Party Insurer: AIG
Third Party Veh No: SJG6036C
Date of Accident: 18/03/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		<i>12</i> \$1,430.10 ✓
2	FRONT BUMPER	1		<i>12</i> \$620.50 X
3	FRONT BUMPER SIDE RETAINER RH	1		<i>12</i> \$45.60 X
4	FRONT BUMPER FOG LAMP COVER RH	1		<i>12</i> \$126.70 X
SUB TOTAL				\$2,222.90
LESS 20%				\$444.58
PARTS TOTAL				\$1,778.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00 X
2	FRONT HEADLAMP CLIPS RH	1		<i>na</i> \$30.00 X
S/N TOTAL				\$80.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT ACCIDENT AREAS & ETC. \$400.00 *100*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREAS & ETC. \$400.00 *220*

TO TUFF KOTE & UNDERSEAL MATERIALS. *na* \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *20*

LABOUR TOTAL \$980.00

KIT

TOTAL \$2,838.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

