

Vehicle Damage Assessment Report for [GBF2040R]

Estimate Created: 25/03/2022 09:22 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 03/03/2023 14:24 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Nissan	Model	NV200
Engine Type			
License Plate Number	GBF2040R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	161,522.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,500.00 WITH 4 WORKING
DAYS

Insurlogic 5 (03/03/2023 14:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BACK DOOR NV 200 EMBLEM N/S		1	85.50	-10.00 %	76.95
REAR BACK DOOR O/S		1	1053.70	-10.00 %	948.33
REAR BACK DOOR LOWER LOCK O/S		1	145.00	-10.00 %	130.50
REAR BACK DOOR INNER RUBBER O/S		1	91.10	-10.00 %	81.99
REAR BACK DOOR INNER TRIM O/S		1	285.00	-10.00 %	256.50
REAR BUMPER		1	485.90	-10.00 %	437.31
REAR BUMPER REFLECTORS		1	58.00	-10.00 %	52.20
REAR BUMPER SPONGE		1	182.00	-10.00 %	163.80
TAILLAMPS		1	304.90	-10.00 %	274.41
REAR END PANEL		1	345.00	-10.00 %	310.50
REAR END PANEL TOP GARNISH		1	145.80	-10.00 %	131.22
REAR END PANEL WEATHERSTRIP		1	221.30	-10.00 %	199.17
REAR BACK DOOR 'DCI' EMBLEM		1	66.80	-10.00 %	60.12
REAR BACK DOOR INNER TRIM CLIP		1	30.00	-10.00 %	27.00

Parts Subtotal 3,150.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
70KM/H STICKER		1.0	10.00	0.00 %	10.00
REAR BACK DOOR GLASS SEALANT O/S		1.0	40.00	0.00 %	40.00
6 PAX STICKER		1.0	10.00	0.00 %	10.00
REAR BUMPER REVERSE SENSOR		1.0	200.00	0.00 %	200.00
REAR CORPORATE STICKER		1.0	480.00	0.00 %	480.00
REAR BUMPER CLIP		1.0	30.00	0.00 %	30.00

Materials Subtotal 770.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	20.00	0.00 %	20.00
TO DISMANTLE REPLACING REVERSE SNESOR	RnR	50.00	0.00 %	50.00
TO DISMANTLE & REFIX BOTH BACK DOOR GLASS	RnR	100.00	0.00 %	100.00
TO DISMANTLE & REFIX BOTH BACK DOOR MECHANISM	RnR	60.00	0.00 %	60.00
TO SPRAY RUST PROOFING	RnR	60.00	0.00 %	60.00
LABOUR FOR PANEL BEATING & REPLACING PARTS	RnR	750.00	0.00 %	750.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO PUTTY SPRAY PAINTING	Full spray	700.00	0.00 %	700.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,040.00

Paint Labor Subtotal 700.00

Labor Subtotal 1,740.00

Summary

Repair Cost 5,660.00

Discount(20 %) (1,132.00)

4,528.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 4,528.00