



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22002626/Upa3q2 Date: 18/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6285M	Veh. Inspected	SMF 3767R
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M03W4J	Excess (\$)	0.00
	Assign From		Assign Date	22/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WVWZZZAUZJUJW120968	Colour	WHITE
	Odometer	40065 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	7 mm
	L/H Front Tyre	225/45 R17	PIRELLI	7 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/03/2022	Inspection Date	23/03/2022
	Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	