$51\,UBI\,AVE\,1, \#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,\,TEL:\\ (065)\,62563561\,\,FAX:\\ (065)\,62564315$

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 25/3/2022

Survey details

Date of loss	18/3/2022
Date of appointment	22/3/2022
Date of survey	22/3/2022
Location of survey	KING'S AUTO REPAIR & SERVICE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SKS 9800T
Make and Model	TOYOTA LEXUS ES250 LUXURY A/T S/R
Date of registration	1/6/2016
Excess	
Market Value	\$100,000.00
Parf Rebate	\$55,053.00
Nett Loss	\$44,947.00

Repair details

|--|

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	

Number of days of repair 10 days (est)

Remarks:

Daamges Consistent

The estimated repair cost of the damaged vehicle is in the region of \$10,000.00-\$12,000.00