

GBG550T Nissan Cabstar

not item

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear left tailgate assy <i>10/500</i>	\$ 1,650.90 ✓
2	1	Rear left tailgate lock mechanism <i>11</i>	\$ 246.10 X
3	1	Rear left tailgate stopper <i>11</i>	\$ 28.80 X
4	5	Rear left tailgate hinges <i>11</i>	\$ 280.90 X
5	1set	Rear left side mudguard <i>Dis</i>	\$ 485.20 ✓
			\$ 2,691.90
		less 10%	\$ 269.19
			<u>\$ 2,422.71</u>

Special Nett Items

1	1	Rear no plate <i>11</i>	\$ 100.00 X
2	1	Rear left tailgate company sticker <i>nu</i>	\$ 450.00 <i>380</i>
3	1	Rear left aluminium side railing assy <i>11</i>	\$ 1,800.00 X
4	1	Rear left tailgate inner aluminium plate assy <i>11</i>	\$ 1,850.00 X
5	1	Rear left wheel rim <i>R</i>	\$ 400.00 X
6	1	Rear left outer tyre <i>11</i>	\$ 350.00 X
7	1	Rear left inner tyre <i>11</i>	\$ 350.00 X
			<u>\$ 5,300.00</u>

Total parts

\$ 7,722.71

*No + no item
nu
22/3/22
2/5 @ 2500
3 days*

GBG550T Nissan Cabstar

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear left affected area and replace rear left damaged parts.	\$ 1,000.00	400
2	To putty and spray painting rear left portion.	\$ 1,000.00	480
3	To apply anti rust proofing to rear left affected area.	\$ 140.00	30
4	To balance rear left wheel.	\$ 11 50.00	X
5	To conduct wheel alignment.	\$ 11 120.00	X
6	Towing service.	\$ 11 200.00	X
Total labour :		\$ 2,510.00	

Total parts : \$ 7,722.71

Total labour : \$ 2,510.00

Total repair cost : \$ 10,232.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-2136-1
 102
 2-1922-49
 S-N-380
 2-910
 3212-49
 202
 2569.