



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG NO. SMG 5456 U

ESTIMATE/NETT	WORKSHOP	CONTACT NO	FAX NO	REFERENCE	DATE	WIP
ESTIMATE	WORKSHOP	CONTACT NO	FAX NO	REFERENCE	DATE	WIP
:	:	:	:	:	:	:
ACCIDENT REPAIRS	UBI ROAD 1	6366 2323	6841 1183	PA/OD/0196/2022/JT	17-Mar-22	16076

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MRS NG LAY HAR (HUANG LIXIA)
ADDRESS	:	107 PETIR ROAD #10-14 SINGAPORE 678275
TELEPHONE	:	HP +65 91863309
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800152412-02
VEHICLE NO	:	SMG 5456 U
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR	:	24/12/2018
ENGINE NO	:	CVK 071522
CHASSIS NO	:	WAUZZZF49KN000657
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	17-Mar-22
PLACE OF ACCIDENT	:	ALEXANDRA HOSPITAL

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 5456 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. TO INSPECT THE DAMAGES.	\$ 2,100.00	500
3	TO RESPRAY REAR BUMPER, RHS TAILLAMP AND REAR END PANELLING.	\$ 2,800.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,452.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5456 U

S/N		PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	Delhd	1	\$ 3,188.00	✓
2	REAR BUMPER FIXING PARTS	new	1	\$ 480.00	x.
3	REAR BUMPER SECURING STRIP	2	1	\$ 249.00	?
4	REAR BUMPER SPOILER	cut	1	\$ 276.00	✓
5	REAR BUMPER TRIM	cut	1	\$ 326.00	✓
6	REAR BUMPER BRACKET - RH	?	1	\$ 130.00	✓
7	REAR LIGHT REFLECTOR - RH	cut	1	\$ 46.00	✓
8	TAIL LIGHT - RH	cut	1	\$ 1,135.00	✓
9	TAIL LIGHT TRIM - RH	xle new	1	\$ 34.00	x
10	REAR BUMPER REINFORCEMENT BEAM	?	1	\$ 1,131.00	?
11	REAR BUMPER REINFORCEMENT SEAL	?	2	\$ 32.00	?
12	REAR BUMPER GUIDE SECTION - LH / RH	2 new	2	\$ 52.00	x
13	REAR BUMPER GUIDE SECTION UPPER - RH	new	1	\$ 51.00	x
14	GUIDE SECTION PIN	new	1	\$ 3.00	x
15	REAR BUMPER HOLDING STRAP - LH / RH	?	2	\$ 188.00	?
16	TELEPHONE AERIAL	xle new	1	\$ 192.00	x.
17	REAR PARKING AID SENSOR - INNER / OUTER	outor	2	\$ 530.00	265.
18	REAR PARKING AID SENSOR SEAL RING	new	4	\$ 10.00	✓
19	REAR VENT TRIM	new	1	\$ 75.00	x.
20	EXHAUST TAIL PIPE - RH	cut	1	\$ 383.00	✓
21	SUNDRIES	?		\$ 250.00	?
TOTAL SPARE PARTS				\$ 8,761.00	
TOTAL LABOUR CHARGES				\$ 5,452.00	
GRAND TOTAL				\$ 14,213.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

VEHICLE NO. SMG 5456 U

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Adrian Lim
22/03/22

Not Authorised, 03 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT