



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Tan Li Kai (Chen Likai) 260 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681 Mobile: 90073103				
		Document No.					
		0					
		Document Date					
		21/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	0	21685	67/DS/SMV0775C
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J060567	2ZR2H39377	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLD3959B ACC DATE:21/03/2022 DRIVE IN:21/03/2022 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00	
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00	
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- REAR END PANEL				60.00	
6	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				360.00	
7	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
8	B	BP-LAB2 REPLACE REAR EH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR RH ACCIDENT AFFECTED AREAS				4320.00	
9	B	BP-RES2 RESPRAY JOB ON REAR RH ACCIDENT AFFECTED AREAS				3540.00	
10	1	T52159-47912 COVER, RR BUMPER	1.00	589.50		589.50	
11	2	T52155-47010 SUPPORT, RR BUMPER	1.00	151.20		151.20	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others		Less		
					Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Li Kai (Chen Likai) 260 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681 Mobile: 90073103			
			Document No.					
			0					
			Document Date					
			21/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	0	21685	67/DS/SMV0775C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU80J060567		2ZR2H39377	60	Sam San Joi	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	3	T52575-47030 RETAINER, RR BUMPER			1.00	62.70		62.70
13	4	S52161-0K040 CLIPS			10.00	4.30		43.00
14	5	T52023-12240 REINFORCEMENT			1.00	230.20		230.20
15	6	T52015-47080 ARM SUB-ASSY, RR			1.00	186.30		186.30
16	7	T76891-47040 SPOILER, RR NO.1			1.00	899.70		899.70
17	8	T58307-47080 PANEL SUB-ASSY, BODY			1.00	738.00		738.00
18	9	T61601-47111 PANEL SUB-ASSY,			1.00	1023.30		1023.30
19	0	T67935-47010 C0 PLATE, BACK DOOR			1.00	192.50		192.50
20	1	T67005-47460 PANEL SUB-ASSY, BACK			1.00	1177.30		1177.30
21	2	T75310-47020 EMBLEM ASSY			1.00	67.20		67.20
22	3	T75442-47080 PLATE, BACK DOOR			1.00	67.20		67.20
23	4	T75441-47130 PLATE, LUGGAGE COMPT			1.00	58.00		58.00
24	5	T81551-47262 LENS & BODY, RR			1.00	730.90		730.90
25	6	TREVSE-47006 16 BACK SENSOR 070 WHITE PEARL			1.00	101.05		101.05
For & on behalf of		Customer's Signature		Charge Summary		Total		15,351.23
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts 6,318.05		GST 7.00%		1,074.59
				Labour 8,670.00		Less		0.00
				Sublet 363.18				
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due		16,425.82

Customer Copy