



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mohammed Shafik Bin Md Som Reg No/Reg Date SLU8304T / 15/12/201 Date In/Mileage 22/03/2022/ 0 Chassis No KNAFX411MJ5755396 Engine No G4FGHH687628 Make/Model KIA/CERATO K3 1.6 A EX CAP Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/03/2022/ 18:05	BLK	282 / Kevin Leong	48515			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2800.00
REPALCE FRT BUMPER, BONNET, SUPPORT, FRT LH FENDER & AFFECTED AREA					2.5 x 400			1000
REPAIR ON FRT RH FENDER								
E PNT98000								1750.00
PAINT WORK ON FRT BUMPER, BONNET, FRT LH DOOR & BOTH FRT FENDER					4 x 350			1400
E PNT88000								120.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								9
M SUNDRY								80.00
TO TOP UP AIRCON GAS								40
M SUNDRY								80.00
TO APPLY SEALANT ON AFFECTED AREA								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
TO SUPPLY & REPLACE FRONT NUMBER PLATE WITH FRAME					BT			
M SUNDRY								80.00
APPLICATION TO BREAK REAR OPC PLATE AND RESEAL					APC			
M SUNDRY								20
SUNDRIES								50.00
M LAMP ASSY-HEAD, LH					1.00	1707.00	20.00	1365.60
M LAMP ASSY-HEAD, RH					1.00	1707.00	20.00	1365.60
M PANEL ASSY-HOOD					1.00	1384.00	20.00	1107.20
M PANEL-FENDER, LH					1.00	482.00	20.00	385.60
M HINGE ASSY-HOOD, RH					1.00	34.00	20.00	27.20
M HINGE ASSY-HOOD, LH					1.00	34.00	20.00	27.20
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M COVER-FR BUMPER					1.00	633.00	20.00	506.40
M MOULDING-FRT BPR LICENSE PLATE					1.00	18.00	20.00	14.40
M LIP ASSY-FRONT BUMPER					1.00	55.00	20.00	44.00

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mohammed Shafik Bin Md Som Reg No/Reg Date SLU8304T / 15/12/201 Date In/Mileage 22/03/2022/ 0 Chassis No KNAFX411MJ5755396 Engine No G4FGHH687628 Make/Model KIA/CERATO K3 1.6 A EX CAP Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/03/2022/ 18:05	BLK	282 / Kevin Leong	48515
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GRILLE ASSY-RADIATOR	BR	1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE,UPR	BR	1.00	54.00	20.00	43.20
M STRIP ASSY-FR BUMPER UPR	BR	1.00	29.00	20.00	23.20
M MOULDING-FRONT BUMPER A/INTAKE	BR	1.00	91.00	20.00	72.80
M ABSORBER-FRONT BUMPER ENERGY	BR	1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER SIDE MTG,LH	BR	1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG,RH	BR	1.00	13.00	20.00	10.40
M ORNAMENT-KIA NO.115	BR	1.00	32.00	20.00	25.60

Estimate

Steve (LKK)
23/3/22, 10.00am

DD-MAL
EXPER-?
PIP
by BR sy
64 djs

Confirm & accepted by

Nett 11,098.40
7% GST on 11098.40 776.89
Total Payable 11,875.29

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.