

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 1333 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00	\$ 1,400.00
3	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	\$ 2,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	\$ 2,000.00
5	TO RESPRAY FRONT BUMPER	\$	1,000.00	\$ 550.00
6	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 520.00
	ADDED LABOUR - SEE ATTACHED	\$	4,040.00	\$ 1,890.00
7	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 14,224.00	\$ 9,624.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1333 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,492.70		
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00		
3	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	1	\$ 254.00	\$	203.20
4	FRONT CENTRE SPOILER	1	\$ 599.00	\$	478.80
5	FRONT WHEEL SPOILER UPPER	2	\$ 164.00	\$	130.24
6	FRONT WHEEL SPOILER LOWER LH	1	\$ 39.00	\$	31.12
7	FRONT WHEEL SPOILER LOWER RH	1	\$ 40.00		
8	NOISE INSULATION FRONT	1	\$ 640.00	\$	512.00
9	NOISE INSULATION REAR	1	\$ 437.00	\$	349.60
10	UNDERBODY TRIM FRONT LH	1	\$ 51.00	\$	40.80
11	UNDERBODY TRIM LH	1	\$ 376.00	\$	300.40
12	UNDERRUN BAR LH / RH	2	\$ 46.00		
13	ALUMINIUM RIM	1	\$ 1,889.00	\$	1,511.20
14	FRONT WHEEL HOUSING LINERS LH / RH	2	\$ 598.00	\$	238.80
15	FRONT WHEEL HOUSING LINERS ATTACHMENT PARTS	1	\$ 176.00		
16	LOCK CARRIER	1	\$ 1,127.00	\$	901.60
17	RADIATOR SUPPORT	2	\$ 85.00		
18	COOLANT PREMIX 1.0 L	6	\$ 282.00	\$	225.60
19	SUBFRAME	1	\$ 2,096.00		
20	FRONT WISHBONE LINK	1	\$ 605.00	\$	483.60
SUB TOTAL SPARE PARTS		:	\$ 12,421.70	\$	5,406.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 1333 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 5,406.96</i>
41	SUSPENSION GUIDE LOWER FRONT LH	1	\$ 1,057.00	
42	SUSPENSION GUIDE UPPER FRONT/ REAR LH	2	\$ 1,150.00	
43	WHEEL BEARING HOUSING LH	1	\$ 1,070.00	
44	SWIVEL JOINT	1	\$ 214.00	<i>\$ 170.80</i>
45	WHEEL HUB	1	\$ 498.00	
46	WHEEL BEARING W FLANGE	1	\$ 273.00	
47	SUSPENSION FORKS LH	1	\$ 293.00	
48	COUPLING ROD	2	\$ 258.00	
49	ANTI- ROLL BAR	1	\$ 478.00	
50	GAS SHOCK ABSORBER	1	\$ 323.00	
51	DRIVE SHAFT	1	\$ 2,999.00	
52	STEERING GEAR	1	\$ 7,318.00	
53	TRACK ROD	1	\$ 109.00	
54	TIE ROD END LH	1	\$ 217.00	
55	FRONT TYRE LH	1	<i>\$ 340.00</i>	<i>\$ 272.00</i>
56	ADDED PARTS - SEE ATTACHED		<i>\$ 12,727.00</i>	<i>\$ 10,178.40</i>
57	ADDED PARTS - SEE ATTACHED		<i>\$ 153.50</i>	<i>\$ 122.80</i>
58	SUNDRIES	1	\$ 600.00	<i>\$ 164.96</i>
TOTAL SPARE PARTS		:	\$ 30,077.50	\$ 16,315.92
TOTAL LABOUR CHARGES		:	\$ 14,224.00	\$ 9,624.00
GRAND TOTAL		:	\$ 44,301.50	\$ 25,939.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-21/04/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0214/2022/NK 28-Mar-22 CHANG 1 of 1 SKW 1333 G AUDI A5 SB 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE. S/N		\$ 400.00	\$ 250.00
2	TO REMOVE AND REINSTALL LHS SILL PANEL TRIM.		\$ 1,200.00	\$ 500.00
3	TO RESPRAY LHS FRONT FENDER AND LHS SILL PANEL TRIM.		\$ 2,400.00	\$ 1,100.00
4	TO RENEW LHS REAR RIM WITH TYRE. S/N		\$ 40.00	\$ 40.00
			\$ 4,040.00	\$ 1,890.00
<u>Parts</u>				
1	FRONT WISHBONE LINK - RH	1	\$ 605.00	\$ 483.60
2	SWIVEL JOINT - RH	1	\$ 214.00	\$ 170.80
3	STONE CHIP GUARD - LH	1	\$ 49.00	\$ 39.20
4	FRONT SUSPENSION CONSOLE - LH	1	\$ 523.00	\$ 418.40
5	RADIATOR AIR GUIDE - LH	1	\$ 72.00	\$ 57.20
6	FRONT FENDER CHROME TRIM - LH	1	\$ 171.00	\$ 136.40
7	1 SET ATTACHMENT PART FOR SILL TRIM	1	\$ 136.00	\$ 108.80
8	1 SET ADHESIVE TAPES FOR SILL TRIM	1	\$ 221.00	\$ 176.80
9	LED HEADLIGHT - LH	1	\$ 8,416.00	\$ 6,732.80
10	RADIATOR AIR GUIDE - LH OUTER	1	\$ 19.00	\$ 14.64
11	RADIATOR AIR GUIDE - RH OUTER	1	\$ 19.00	\$ 14.64
12	ALUMINIUM RIM - LH REAR	1	\$ 1,889.00	\$ 1,511.20
13	TYRE - LH REAR	1	\$ 385.00	\$ 308.00
14	RUBBER VALVE	1	\$ 8.00	\$ 5.92
		MATERIALS	\$ 12,727.00	\$ 10,178.40
		LABOUR	\$ 4,040.00	\$ 1,890.00
		TOTAL	\$ 16,767.00	\$ 12,068.40

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0214/2022/NK 27-Apr-22 CHANG 1 of 1 SKW 1333 G AUDI A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BRACKET FOR LOCK CARRIER	\$ 154.00	\$ 122.80
	GRAND TOTAL	\$ 154.00	\$ 122.80

For Premium Automobiles Pte Ltd

Authorised Signature