



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 28/3/2022

Survey details

Date of loss	5/3/2022
Date of appointment	23/3/2022
Date of survey	24/3/2022
Location of survey	SPEEDWAY MOTOR PL

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	FBS 5428T
Make and Model	HONDA NSS300A
Date of registration	28/5/2021
Excess	
Sum Insured	\$14,000.00
Parf Rebate	\$7,980.00
Nett Loss	\$6,020.00

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	3 days (est)

Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$3,000.00-\$4,000.00