



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22002692/Gqy3e2 Date: 17/05/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YN 3261Z
	Policy No.	Z21VC05008689	Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025586	Excess (\$)	2,000.00
	Assign From	GERALD POH	Assign Date	23/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi FM65FM1RDEA	c.c	7545
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	FM65FMA00218	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	11 R22.5	SPEEDEX	6 mm
	L/H Front Tyre	11 R22.5	SPEEDEX	6 mm
	R/H Rear Tyre	11 R22.5 (D)	SPEEDEX	6/6 mm
	L/H Rear Tyre	11 R22.5 (D)	SPEEDEX	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/03/2022	Inspection Date	23/03/2022
	Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks				
	A)THE MARKET VALUE IS S\$12,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			