




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623			Ref: CS3/SMO22002696/Uvy3e2 Date: 06/04/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMZ 7811P	Veh. Inspected	SJB 278L	
Policy No.	D21MTPV01007808	Coverage (\$)	0.00	
Claim No.	CMTD2200976/LOR	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	23/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA5 SP (A)	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JM6CR10F170106333	Colour	WHITE	
Odometer	278247 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/55 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	22/03/2022	Inspect Date / Time	23/03/2022 ( 03:35 PM )	
Survey held at	Blk 13 Defu Lane 10 #01-432 Singapore 539194			
Repairer	KNW CAR SPRAY			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$3,500				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO22002696/Uvy3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.