

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 7332L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	941.30	552.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	282.25	-
1	FRONT BUMPER SPONGE	CRACKED	212.50	185.00
1	FRONT BUMPER SIDE RETAINER RH	DAMAGED	68.70	35.00
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	179.30	-
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	311.20	-
1	FRONT GRILLE	CRACKED	499.30	375.00
1	FRONT GRILLE LOGO	NECESSARY	104.50	55.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	845.60	-
1	RH FRONT FENDER	BUCKLED	623.40	623.40
1	RH FRONT FENDER INNER COWLING	NOT NECESSARY	187.60	-
1	WIPER WASHER TANK	CRACKED	218.10	141.00
1	HEADLAMP RH	CRACKED	809.40	809.40
	LESS 25% DISCOUNT		-1,320.79	-693.95
			3,962.36	2,081.85
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	30.00
1	RH FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	FRONT NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	60.00	-
			240.00	60.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		800.00	500.00
	LABOUR FOR SPRAYPAINTING.		800.00	400.00
	WIRING CHECK.		60.00	30.00
	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS.		200.00	30.00
			1,860.00	960.00
	GRAND TOTAL		6,062.36	3,101.85

Report Ref No. CS/SMO22002698/Aty3n2





RECOMMENDED COST OF LUMP SUM REPAIRS	2,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO22002698/Aty3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.