

TP Budget Direct. SIK 2794A. 2014 May.

Hui Kong. Volkswagen Golf. 1395cc

WVWZZZAUZEW 361449.

Front Number Plate	Dented	30(SN)	✓
Front Number Plate Holder	Deformed	30(SN)	✓
Front Bumper	Deformed	1098	✓
Front Bumper Clips	NEC	50(SN)	✓
Front Bumper Lower Grille	Not NEC	228	✗
Front Bumper Sponge	Cracked	148	✓
Front Bumper Reinforcement	Not NEC	578	✗
Front Bumper Top Beam	Cracked	209	✓
Front Grille	At	485	✓
Front Grille Clips	NEC	30(SN)	✓
Front Grille Logo	At	112	✓
Handcup x 02	Not NEC	1955 x 2 = 3910	✗

2052 S.N. 110
1846.80

SKN 2794A.

Panel Beating
Spray Painting.
Wiring.

~~500~~ 250
~~500~~ 250
~~50~~ 30 430

total: 2486.80

H/s: 12 K.

02 Days.