LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jacqueline Tan Date: 28 Mar 2022

Preliminary Advice

Vehicle No : SBV3388Y Accident Date : 19/03/2022

Make : AUDI RS6 Policy No.

DMPCSNA00261722101

Date of Inspection : 25/3/2022 Est. Duration of Repair : 6

Inspection At : PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,102.00
Revised Amount	:S\$	16,515.50
Check Items (Estimated)	:S\$	3,209.00
Total	:S\$	19,724.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$

 Pre-Accident Value
 :S\$ 146,000.00

 COE / PARF Rebate
 :S\$ 97,902.00

Salvage Value :S\$

Margin for Repair :S\$ 48,098.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

⁽ X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .