

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0233/2022/JT
DATE : 25-Mar-22
WIP : 17064

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 1/4/22

YOUR INSURED VEH NO : SJR 8036 G

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR RAJAT NAG
ADDRESS : 3 LUXUS HILL DRIVE
SINGAPORE 804806
TELEPHONE : HP +65 98204245
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SP200103466-01
VEHICLE NO : **SMJ 3816 L**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 28/2/2019
ENGINE NO : CVK 074456
CHASSIS NO : WAUZZZF55KA015107
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Mar-22
PLACE OF ACCIDENT : CTE BETWEEN AMK 1 &AMK 3 EXIT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3816 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND LHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	
3	TO RESPRAY REAR BUMPER, REAR LID AND LHS TAILLAMP PANEL.	\$ 3,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3816 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,011.00	
2	REAR BUMPER FIXING PARTS	1	\$ 172.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER CHROME TRIM	1	\$ 1,139.00	
5	REAR LIGHT REFLECTOR - LH	1	\$ 46.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	
7	REAR BUMPER SEAL	2	\$ 32.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 98.00	
9	REAR BUMPER GUIDE SECTION UPPER - LH / RH	2	\$ 52.00	
10	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 530.00	
11	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	
12	TAIL LIGHT	1	\$ 1,269.00	
13	TAIL LIGHT TRIM - LH	1	\$ 34.00	
14	TAIL LIGHT INNER - LH	1	\$ 1,135.00	
15	TAIL LIGHT TRIM INNER - LH	1	\$ 34.00	
16	REAR PACKING ADHESIVE	1	\$ 21.00	
17	AUDI EMBLEM	1	\$ 163.00	
18	A5 EMBLEM	1	\$ 104.00	
19	BOOT LID CONTROL UNIT	1	\$ 454.00	
20	AERIAL FOR KESSY	1	\$ 120.00	
SUB TOTAL SPARE PARTS		:	\$ 9,804.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3816 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AERIAL RETAINER - LH	1	\$ 29.00	
22	TELEPHONE AERIAL	1	\$ 192.00	
23	EXHAUST TAILPIPE - LH	1	\$ 153.00	
24	REAR NO PLATE	S/N	\$ 60.00	
25	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 10,538.00	
TOTAL LABOUR CHARGES		:	\$ 5,152.00	
GRAND TOTAL		:	\$ 15,690.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT