



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC21011664/Gvy3e2-1

Date: 28/04/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 7967U	Veh. Inspected	SLC 5508L
Policy No.		Coverage (\$)	0.00
Claim No.	21/21/21/VC05/025141	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	24/03/2022

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM4278G0338793	Colour	WHITE
Odometer	81915 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/11/2021	Inspection Date	16/11/2021
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**