

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAN	ICE SINGAPORE PTE LTD	Ī	Ref:	CS/AIS22002760/Uvy3n2	
	79 ROBINSON RO #09-01 SINGAPOR		I	Date:	06/04/2022	
			(Code:	AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJW 3286H	Veh. Inspected		SJM 9460J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22004306/SL	Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		25/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FREED (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	GB31025636	Colour		WHITE	
	Odometer	271336 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/65 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	185/65 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	185/65 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	185/65 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/03/2022	Inspection Date	•	25/03/2022	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				