



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY

Ref: CC4/ASM22002812/Uea3q2
Date: 13/06/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3267S	Veh. Inspected	SJJ 4551D
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M03WUM	Excess (\$)	0.00
Assign From		Assign Date	28/03/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM RSZ (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61083298	Colour	BROWN
Odometer	263065 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	PIRELLI	6 mm
L/H Front Tyre	205/55 R17	PIRELLI	6 mm
R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
L/H Rear Tyre	205/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/03/2022	Inspection Date	28/03/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**