



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM22002820/Uvy3e2 Date: 13/04/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 1056H	Veh. Inspected	SLP 8598M
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03WH0	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0158967	Colour	BLUE
	Odometer	217028 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TOYO	6 mm
	L/H Front Tyre	205/60 R16	TOYO	6 mm
	R/H Rear Tyre	205/60 R16	TOYO	6 mm
	L/H Rear Tyre	205/60 R16	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
5. General Information				
	Accident Date	21/03/2022	Inspect Date / Time	28/03/2022 (01:00 PM)
	Survey held at	1 Kaki Bukit Avenue 6 #01-52 Autobay@Kaki Bukit		
	Repairer	NEO AUTOMOTIVE PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM22002820/Uvy3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.