



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22002836/Vqy3e2 Date: 06/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 9534X	Veh. Inspected	SGY 1387M
	Policy No.	GA567548	Coverage (\$)	0.00
	Claim No.	S2M03WWE	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA STREAM	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	RN61048462	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R15	YOKOHAMA	5 mm
	L/H Front Tyre	205/65 R15	YOKOHAMA	5 mm
	R/H Rear Tyre	205/65 R15	YOKOHAMA	5 mm
	L/H Rear Tyre	205/65 R15	YOKOHAMA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2022	Inspection Date	29/03/2022
	Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	