

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HL ASSURANCE F	R	ef:	CS3/HLA22002837/Vty3		
	11 KEPPEL ROAD #11-01 ABI PLAZA	D	ate:	28/03/2022		
			С	ode:	HLA	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMP 3046K	Veh. Inspected		SLR 2303B	
	Policy No.	MP319845	Coverage (\$)		0.00	
	Claim No.	MPC03267/GN	Excess (\$)		0.00	
	Assign From	GRACE NG	Assign Date		28/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model		C.C		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	26/03/2022	Inspection Date		28/03/2022	
	Survey held at	GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					