



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002838/Uvy3n2	
			Date: 12/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 2587K	Veh. Inspected	SLQ 3639G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201020/AGC	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ S500L AMG (A)	c.c	4663
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2221822A272148	Colour	SILVER
	Odometer	86350 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R20	PIRELLI	6 mm
	L/H Front Tyre	245/40 R20	PIRELLI	6 mm
	R/H Rear Tyre	275/35 R20	PIRELLI	6 mm
	L/H Rear Tyre	275/35 R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2022	Inspection Date	28/03/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	