



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002838/Uvy3n2	
			Date: 12/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 2587K		Veh. Inspected	SLQ 3639G
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2201020/AGC		Excess (\$)	0.00
Assign From	MELVIN YE		Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ S500L AMG (A)		c.c	4663
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	WDD2221822A272148		Colour	SILVER
Odometer	86350 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R20	PIRELLI	6 mm	
L/H Front Tyre	245/40 R20	PIRELLI	6 mm	
R/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
L/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/03/2022		Inspection Date	28/03/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	