

**ASSIGNMENT**

From:

Date:

Veh No:

*SMN 5372R*

Regn:

*16/08/19*

Estimated Cost:

Type: *M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**6* OD / TP / WS / TP RES / OD RES / EVA / INV / MVTruck / Trailer or *CA /*

To Inspect Vehicle No:

*SMN 5372R*

Make:

*KIA Cerato 1.6 EX cc 1591*

at Workshop m/s

*Lee brook*

Colour:

*Black*A/C: *Insured / Std / NI / NA*

of

Sp. Reading

*43166*T/Radio: *Insured / Std / NI / NA*

Insured:

Eng/No:

Policy No.

C/No:

*KNAF3416MK5045850*

Claims No.

Gen. Cond: *Good / Fair / Poor / Burnt*

Sum Insured:

Excess:

Steering: *Inorder / Jammed / Leaked / Burnt or*

(Client's Record)

Brake: *Inorder / Jammed / Leaked / Burnt or*

Make of Veh:

Modi: *Nil / S/Rim / STD A/Rim or*

(Policy Condition)

Tyre Size:

F:

R:

*205/55-R16*

Remark: The veh had commenced its

repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

*\$79k.*

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

*6*

days

Res.:

Yes or No

D.O.A.

*27/03/22*

D.O.I.

*28/3/22*

Lum Sum:

*20*

%

3 Val.:

Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

*189f*

Date:

Person Contacted:

*LTA 31972*Des. of Damages: *Frt / Rear / O/S / N/S / U/C / Rooftop or**Rear o/c*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Dep 10k.**have video*

*5/4/22 1/5 \$ ~~5500~~ informed AH hook*  
*5,500.00*

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) *S + RS* *SI*☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SHC3237D

## ESTIMATE

DATE : 30.03.2022

VEHICLE NO : SMN5372R

MAKE/MODEL : KIA CERATO

ACC DATE : 27.03.2022

Not Authorized  
28/3/22 5,500.00  
1/5 \$ ~~5500~~  
6 days

| PARTICULAR |                                                           | UNIT PRICE | AMOUNT          |
|------------|-----------------------------------------------------------|------------|-----------------|
| QTY        |                                                           | SS         | SS              |
|            | <u>LIST PRICE</u>                                         |            |                 |
| 1          | 1 REAR BUMPER 3.5                                         | 688.00     | 688.00 ✓        |
| 2          | 1 REAR BUMPER DISFUSER 7.5                                | 326.00     | 326.00 ✓        |
| 3          | 1 REAR BUMPER LAMP - RH CR                                | 189.00     | 189.00 ✓        |
| 4          | 1 REAR BUMPER LAMP GARNISH - RH 7.5                       | 122.00     | 122.00 ✓        |
| 5          | 1 REAR BUMPER UNDERCOVER 7.5                              | 126.00     | 126.00 ✓        |
| 6          | 1 REAR BUMPER REINFORCEMENT 7.5                           | 485.00     | 485.00 ✓        |
| 7          | 2 REAR BUMPER SIDE RETAINERS - RH/LH 0.5 CR 1/5 CR 1/5 CR | 55.00      | 110.00 1/5 CR   |
| 8          | 1 REAR BOOT LID ^ ^                                       | 1,297.00   | 1,297.00 X      |
| 9          | 1 REAR BOOT KIA LOGO ^ ^                                  | 85.00      | 85.00 X         |
| 10         | 1 REAR BOOT EMBLEM 'CERATO' ^ ^                           | 89.00      | 89.00 X         |
| 11         | 1 REAR BOOT W/STRIP ^ ^                                   | 146.00     | 146.00 X        |
| 12         | 1 REAR END PANEL 7.5 / 7.5                                | 473.00     | 473.00 ✓        |
| 13         | 1 REAR END PANEL GARNISH ^ ^                              | 192.00     | 192.00 X        |
| 14         | 1 REAR FENDER - RH 6.5                                    | 1,265.00   | 1,265.00 ✓      |
| 15         | 1 REAR FENDER AIR VENT CR                                 | 89.00      | 89.00 ✓         |
| 16         | 1 REAR FENDER INNER SHIELD 7.5                            | 132.00     | 132.00 ✓        |
| 17         | 1 REAR FENDER INNER TRIM - RH 7.5                         | 315.00     | 315.00 ✓        |
| 18         | 1 REAR FLOOR BOARD ^ ^                                    | 365.00     | 365.00 X        |
| 19         | 1 REAR SHOCK ABSORBER - RH ^ ^                            | 286.00     | 286.00 X        |
| 20         | 1 REAR WHEEL HUB BEARING ^ ^                              | 459.00     | 459.00 X        |
| 21         | 1 REAR TAILLAMP - RH CR 6.5                               | 675.00     | 675.00 ✓        |
| 22         | 1 REAR WINDSCREEN MOULDING ^ ^                            | 112.00     | 112.00 X        |
|            |                                                           |            | 8,026.00        |
|            |                                                           | LESS 10%   | 802.60          |
|            |                                                           |            | <u>7,223.40</u> |

## SPECIAL NETT ITEMS

|   |                                     |        |                 |
|---|-------------------------------------|--------|-----------------|
| 1 | 1 (SET) REAR BUMPER CLIP 1.5        | 45.00  | 45.00 ✓         |
| 2 | 1 (SET) REAR REVERSE SENSOR 5.5     | 280.00 | 280.00 2.5      |
| 3 | 1 REAR SPORT WHEEL ^ ^              | 550.00 | 550.00 X        |
| 4 | 1 REAR TYRE ^ ^                     | 300.00 | 300.00 X        |
| 5 | 1 (SET) REAR WINDSCREEN SEALANT ^ ^ | 80.00  | 80.00 X         |
|   |                                     |        | <u>1,255.00</u> |

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

| PARTICULAR                                                 | UNIT PRICE | AMOUNT          |
|------------------------------------------------------------|------------|-----------------|
| QTY                                                        | SS         | SS              |
| <b>LABOUR CHARGES :</b>                                    |            |                 |
| 1 TO CHECK REAR ELECTRICAL WIRING                          |            | 50.00 20        |
| 2 TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR   |            | 120.00 80       |
| 3 TO REMOVE & REPLACE REAR UNDERCARRIAGE PARTS             |            | 200.00 X        |
| 4 TO REMOVE & REPLACE REAR WINDSCREEN GLASS                |            | 150.00 X        |
| 5 TO CONDUCT COMPUTERISED WHEEL ALIGNMENT                  |            | 120.00 60       |
| 6 TO TUFF KOTE                                             |            | 100.00 50       |
| 7 TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS            |            | 1,080.00 900    |
| 8 TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS |            | 1,400.00 1200   |
|                                                            |            | <u>3,220.00</u> |

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 11,698.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4874  
102  
P-4386.60  
5-N-245.00  
L-2310  
6941.60  
202  
5553.28