

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #07-03 Singapore 138498				
		Document Date 26/03/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXBW Q2	24/08/2017	SLR6737G	0	14118	66TP/SLR6737G/260322
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU303570071		2ZRS085387	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: ACC DATE:25/03/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50✓ 100.00	
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				QR 80.00✓	
3	B	BP-LAB2 REPL ACC AFF PRTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				720 1440.00✓	
4	B	BP-RES2 RESRPAY ACC AFF AREA				590 1180.00✓	
5	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00✓	
6	1	U53395-47040 SEAL, HOOD TO FR END	1.00	54.70		54.70✓	
7	2	S52161-0K040 PIECE,RR BUMPER	4.00	4.30		17.20✓	
8	3	U52115-47050 SUPPORT, FR BUMPER	1.00	84.70		84.70✓	
9	4	U52116-47050 SUPPORT, FR BUMPER	1.00	84.70		84.70✓	
10	5	U52119-47962 COVER, FR BUMPER	1.00	547.10		547.10✓	
11	6	U52114-47190 BRACKET, FR BUMPER	1.00	109.80		109.80✓	
12	7	U52127-47907 COVER, FR BUMPER	1.00	31.10		31.10✓	
13	8	U52128-47906 COVER, FR BUMPER	1.00	31.10		31.10✓	
14	9	U53112-47240 GRILLE, RADIATOR,	1.00	180.30		180.30✓	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 1967000862

GST Reg No. : MR-8500000-9

No 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1168



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 3 Media Close #07-03 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 26/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	24/08/2017	SLR6737G	0	14118	66TP/SLR6737G/260322		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU303570071		2ZRS085387	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
15	0	U51420-47030 COVER ASSY, ENGINE				1.00	197.00		197.00
16	1	U52611-47140 ABSORBER, FR BUMPER				1.00	84.20		84.20
17	2	U52021-47110 REINFORCEMENT				1.00	758.70		758.70
18	3	U53101-47081 GRILLE SUB-ASSY,				1.00	367.20		367.20
19	4	U75310-47060 EMBLEM ASSY,				1.00	96.60		96.60
20	5	U81210-47020 LAMP ASSY, FOG, RH				1.00	1009.10		1009.10
21	6	U81220-47020 LAMP ASSY, FOG, LH				1.00	1009.10		1009.10
22	7	U81145-47691 UNIT, HEADLAMP				1.00	2794.80		2794.80
23	8	U81185-47691 UNIT, HEADLAMP				1.00	2794.80		2794.80
<i>Stave (LKK)</i> 23/5/22, 4.30p <i>M L</i> <i>PIP</i> <i>by BL</i> <i>3 4/5</i>						LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Must be resurveyed and is subject to final approval from Insurance Company			
						For & on behalf of Borneo Motors (Singapore) Pte Ltd Acknowledged by Repairer Signature: _____			
Customer's Signature						Charge Summary		Total	
Please acknowledge receipt of vehicle						Parts 10,252.20		13,232.20	
						Labour 2,900.00			
						Sublet 80.00		GST 7.00% 926.25	
						Lubrication/Fluid 0.00		Less 0.00	
						Others 0.00		Amount Due 14,158.45	

Customer Copy