



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: DERICK ONG			Ref: CS/ASM22002859/Avy3s2 Date: 26/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7548Z	Veh. Inspected	FBS 6358E
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03WVX	Excess (\$)	0.00
	Assign From	DERICK ONG	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ADV150	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH1KF6114MK035145	Colour	BLACK
	Odometer	32318 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70 R14	METZELER	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	METZELER	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2022	Inspection Date	29/03/2022
	Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	