




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM22002865/Rqy3e2 Date: 06/04/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 9968G	Veh. Inspected	SMS 9516R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03WU9	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	29/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA HYBRID 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	NHP1707177644	Colour	RED
	Odometer	110578 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	DAVANTI	6 mm
	L/H Front Tyre	185/60 R15	DAVANTI	6 mm
	R/H Rear Tyre	185/60 R15	DAVANTI	6 mm
	L/H Rear Tyre	185/60 R15	DAVANTI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
5. General Information				
	Accident Date	25/03/2022	Inspect Date / Time	29/03/2022 (01:54 PM)
	Survey held at	39 WOODLANDS CLOSE #01-34/35 MEGA@WOODLANDS		
	Repairer	FA AUTOWORKS PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM22002865/Rqy3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.