

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMCVSNA00139292100

Claims No. SNM22D202069/C02/IRENE

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

207/11009

Nett 48137

24/5/22 21/2 & 21820.08 informed Suhelmi (red 6200.11, 22%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 24/5/22-typist

Days Of Repair: 18

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$21,820.08)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	012Z
Vehicle Details	
Vehicle No.:	SND7849K
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2022
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	R16B25502374
Chassis No.:	MRHFC5650JT002049
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,964.00
Original Registration Date:	12 Dec 2018
First Registration Date:	12 Dec 2018
Transfer Count:	1
Actual ARF Paid:	\$19,964.00 9982
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2028
PARF Rebate Amount:	\$14,973.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$18,890.00
Total Rebate Amount:	\$33,863.00

The information contained herein is correct as at 29 Mar 2022

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Honda Vezel 1.5A Sensing.



Excellent Condition, Non PMV,
Good Short Term Ownership.
Grandeur Motors Pte
Ltd [StarAd](#)

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

« Back (1 2) Next »

Sort by 20 results/page

21 vehicles



honda civic 1.6

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda civic 1.6		Any	Any	2018	Any	Any	Any	Available
	Honda Civic 1.6A VTI		\$81,800	\$12,000 /yr	26-Mar-2018	1,597 cc	-	Sedan	Available
	Warranty From Agent Until 2023! Well Kept And Maintained! Drives Like New! Trade In Or Consign Your Current Vehicle! High In House L... Monster Motors Pte Ltd Posted: 29-Mar-2022								PREMIUM AD
	Honda Civic 1.6A VTI		\$82,800	\$11,870 /yr	21-May-2018	1,597 cc	65,000 km	Sedan	Available
	\$2000 Loan Rebate. Fully Maintain By Agent (Kah Motors) With 5Yrs Warranty Till May 2023. Well Kept In Almost New Condition On Bot... Posted: 29-Mar-2022								
	Honda Civic 1.6A VTI		\$79,800	\$11,990 /yr	01-Feb-2018	1,597 cc	57,000 km	Sedan	Available
	1 Owner Only. From Kah Motor With Full Servicing Records Since Day 1 With All Receipts Intact. Accident Free With Original Paintwork... This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More Posted: 28-Mar-2022								
	Honda Civic 1.6A VTI		\$83,800	\$11,670 /yr	19-Jul-2018	1,597 cc	74,000 km	Sedan	Available
	Only 1 Owner! KAH Motor Warranty Till July 2023! Drive/Feels Like A New Unit! Immaculate Interior And Exterior Condition, 120 Points C... Posted: 28-Mar-2022								PREMIUM AD
	Selling your Honda Civic? Receive \$3,000 more than trade-in when you sell your Honda Civic with sgCarMart Quotz. Get Free Valuation with sgCarMart Quotz								
	Honda Civic 1.6A VTI		\$83,800	\$11,850 /yr	20-Jun-2018	1,597 cc	35,323 km	Sedan	Available
	Very Low Mileage Done At 35,323 Km Only! 1 Owner! Fully Serviced And Very Well Maintained By KAH Motors With 5 Years Full Warranty... Car Express Auto Trading Posted: 27-Mar-2022								
	Honda Civic 1.6A VTI		\$85,800	\$12,050 /yr	06-Jul-2018	1,597 cc	43,880 km	Sedan	Available
	Immediate Transfer Of Ownership Upon Collection. 1 Owner. Very Low Mileage Done. 100% Loan Available. Fully Serviced By Kah Motor... Guan Motor Trading Posted: 26-Mar-2022								PREMIUM AD
	Honda Civic 1.6A VTI		\$82,800	\$11,750 /yr	12-Jun-2018	1,597 cc	54,000 km	Sedan	Available
	Fully Agent Maintained By (KAH MOTOR) Till Jun 2023, Interest As Low As 1.88%! Powerful And Responsive. Low Maintenance. Excellen... EDM Cars Pte Ltd Posted: 25-Mar-2022								PREMIUM AD
Compare	Honda Civic 1.6A VTI		\$86,800	\$12,500 /yr	24-May-2018	1,597 cc	-	Sedan	Available



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/03/2022 15:11 (SGT)
Date of Accident	24/03/2022 18:11 (SGT)
Exact Location of Accident	Near PUB Recreation Club, Singapore
Additional Location Information	ALONG BRADDELL ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND7849K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YAP YING JIE CLEMENT
NRIC No	SXXXX012Z
Email Address	clementyyj@outlook.com
Mobile Phone No	(Phone) +65-91693535
Alternative Phone No	+65-91693535

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SD22V04128/VPE/R00
Cover Note Number	-

DRIVER

Name of Driver	YAP YING JIE CLEMENT
NRIC No	SXXXX012Z



Date Of Birth	19/07/1990
Occupation	Indoor
Date Of Driving Pass	31/01/2012
Driving experience	10 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91693535
Alt. Phone Number	+65-91693535
Email Address	clementyyj@outlook.com
Address	2 WOODLEIGH CLOSE
Address complement	02-06
Postcode	357900
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio Division Headquarters
Police Station Phone No	(Phone) +65-18002180000
Alt. Police Station Phone No	(Fax) +65-64814246
Police Station Address	51 Ang Mo Kio Avenue 9 Singapore 569784
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE5948Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	-
Contact Number	(Phone) +65-96155910
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	YAP YING JIE CLEMENT
Gender	-
Phone No	(Phone) +65-91693535
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SND7849K
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

Vehicle
Number: 3ND 78496

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **reputate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


25.3.22
10.12.00

Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Person(s)'s Signature
Name:
NRIC No.:

Vehicle Number: SND7849E

SKETCH PLAN



A: SND7849E

B: XE59489

X: vehicle tried to change lane

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

25.3.22
10.30m

Driver's Signature (if driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name:
Title/Position:



**SINGAPORE
POLICE FORCE**



F/20220324/7073

1 of 3

POLICE REPORT (NP299)

Report No. F/20220324/7073

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No:1800-2180000

Date/Time Report Made 24/03/2022 22:56	Vide Report No.	Station Diary No.
Name Of Informant YAP YING JIE CLEMENT	Address 2 WOODLEIGH CLOSE #02-06 SINGAPORE 357900	
ID Type / ID No. NRIC NO / S9026012Z	Contact No. Home/Office:	Mobile: 91693535
Nationality SINGAPORE CITIZEN	Email Address clementyyj@outlook.com	
Occupation Advocate/Solicitor	Sex Male	Age 31
Institution/School Name	Date of Birth 19/07/1990	Race Chinese
Date/Time Of Incident 24/03/2022 18:10 - 24/03/2022 18:15	Location Of Incident BRADDELL ROAD	

Brief details.

I was driving my motor vehicle SND7849K along Braddell Road at about 6.11pm. As I was driving, the car in the lane to my left juttet out as it intended to sift into my lane.

I thus came to a stop as otherwise I would have hit the car in front.

However, moments later a Tipper Truck XE 4948Y hit the rear of my car with great force, throwing my entire car forward and caving in the entire rear portion of my car. I suffered injuries from the collision and was given 7 days of medical leave that same night.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/03/2022 22:56
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



F/20220324/7073

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20220324/7073

The driver of the Tipper Truck had driven in a reckless manner and failed to keep a proper safety distance - likely the driver was exceeding the speed limit or I would not have suffered such significant injuries.

The driver of the Tipper Truck is an S Pass Holder. His name is Govindasamy Sarathkumar. His S Pass No. is 0 36164468. His employer is Kok Tong Construction Pte Ltd. His Fin No. is G2394736L. His date of birth is 27 June 1991. His nationality is Indian.

The driver represented that his boss was one Ng Kin Hoe, with HP No. 9615 5910.

Subjects Involved			
Suspect			
Person Name	Govindasamy Sarathkumar		
ID Type	FIN NO	ID No	G2394736L
Gender	Male	Age	30-31
Race	Indian	Language	Unknown
Address	Unknown SINGAPORE 000000	Home/Office No	96155910
Mobile No	96155910	Complexion	Dark
Build	Medium	Height About	170cm
Attire Last Worn	Red Shirt and Jeans	Hair Colour	Black
Hair Style	Medium-Natural Curls	Relation To Informant	-
Habits & Oddities	Employed by Kok Tong Construction Pte Ltd		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
24/03/2022 22:56

Classification Of Case:



**SINGAPORE
POLICE FORCE**



F/20220324/7073

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20220324/7073

Victim			
Person Name	YAP YING JIE CLEMENT		
ID Type	NRIC NO	ID No	S9026012Z
Gender	Male	Age	31
Race	Chinese	Language	English
Occupation	Advocate/Solicitor	Address	2 WOODLEIGH CLOSE #02-06 SINGAPORE 357900
Mobile No	91693535	Is Informant A Victim?	Yes
Person Name	YAP YING JIE CLEMENT (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
24/03/2022 22:56

Classification Of Case:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SND7849K

Chassis No : MRHFC5650JT002049

Model : CIVIC 1.6 VTI YM2018

Owner's Name : YAP YING JIE CLEMENT

Ins Policy No. :

Date of Accident : 24/3/2022

Document No. : SQT22000814 Page 1

Date : 25. Mar 2022

Customer No. : WZC008

Svc Advisor : SUHELMI

Engine No : R16B25502374

Date | Time : 25. Mar 2022 11:51:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YAP YING JIE CLEMENT OWNER INSURER: LIBERTY ACC DATE: 24/03/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: XE5948Y						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>Dis Dis</i>	1	617.20	25	462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>Dis</i>	1	41.60	25	31.20	2.18	33.38
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE <i>Dis</i>	1	8.90	25	6.67	0.47	7.14
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE <i>Dis</i>	1	8.90	25	6.67	0.47	7.14
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>Dis</i>	1	2.60	25	1.95	0.14	2.09
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>Dis</i>	1	2.60	25	1.95	0.14	2.09
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>Dis</i>	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>Dis</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>Dis</i>	7	2.30	25	12.07	0.84	12.91
33505-TEA-T01	REFLECTOR ASSYR.RR. <i>Dis</i>	1	8.20	25	6.15	0.43	6.58
33555-TEA-T01	REFLECTOR ASSYL.RR. <i>Dis</i>	1	8.20	25	6.15	0.43	6.58
66100-TEC-307ZZ	PANEL SETRR. <i>Body</i>	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE <i>Dis</i>	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE <i>Dis</i>	1	30.50	25	22.87	1.60	24.47
65550-TEA-T00ZZ	PAN COMPSPARE TIRE <i>Dis</i>	1	247.30	25	185.47	12.98	198.45
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>Body</i>	1	812.30	25	609.22	42.65	651.87
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE <i>Body</i>	1	812.30	25	609.22	42.65	651.87
63321-TEA-T00ZZ	GUTTERR.RR.UPPER <i>Dis</i>	1	33.50	25	25.12	1.76	26.88

Printed on 25/3/2022 3:16:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SND7849K

Chassis No : MRHFC5650JT002049

Model : CIVIC 1.6 VTI YM2018

Owner's Name : YAP YING JIE CLEMENT

Ins Policy No. :

Date of Accident : 24/3/2022

Document No. : SQT22000814 Page 2

Date : 25. Mar 2022

Customer No. : WZC008

Svc Advisor : SUHELMI

Engine No : R16B25502374

Date | Time : 25. Mar 2022 11:51:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
63721-TEA-T00ZZ	GUTTERL.RR.UPPER	1	33.50	25	25.12	1.76	26.88
63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT	1	69.30	25	51.97	3.64	55.61
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT	1	69.30	25	51.97	3.64	55.61
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	114.80	25	86.10	6.03	92.13
75701-TBA-A10	EMBLEM,H-MARK	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.22	3.37
74851-TEA-003	LOCK ASSYTRUNK	1	84.90	25	63.67	4.46	68.13
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	37.60	25	28.20	1.97	30.17
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	51.10	25	38.32	2.68	41.00
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	51.10	25	38.32	2.68	41.00
74895-TEX-Y01	GARNISH ASSYR.TRUNK HINGE	1	17.50	25	13.12	0.92	14.04
74896-TEX-Y01	GARNISH ASSYL.TRUNK HINGE	1	17.50	25	13.12	0.92	14.04
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	68.70	25	51.52	3.61	55.13
84542-TET-H00	BOX COMPTOOL	1	43.40	25	32.55	2.28	34.83
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
73500-TEA-T02	GLASS ASSYR.QUARTER WINDSHIELD	1	155.90	25	116.92	8.18	125.10
73550-TEA-T02	GLASS ASSY.,L.QUARTER WINDSHIELD	1	155.90	25	116.92	8.18	125.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
33500-TEA-T01	TAILLIGHT ASSYR.	1	298.40	25	223.80	15.67	239.47
33550-TEA-T01	TAILLIGHT ASSYL.	1	321.10	25	240.82	16.86	257.68
34150-TEX-Y01	LIGHT ASSYR.LID	1	139.60	25	104.70	7.33	112.03
34155-TEX-Y01	LIGHT ASSYL.LID	1	139.60	25	104.70	7.33	112.03
39530-TEA-H01	CAMERA ASSY,RR VI	1	360.20	25	270.15	18.91	289.06
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	2	155.40	25	233.10	32.63	265.73
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	32.10	25	24.07	1.68	25.75

Printed on 25/3/2022 3:16:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SND7849K
Chassis No : MRHFC5650JT002049
Model : CIVIC 1.6 VTI YM2018
Owner's Name : YAP YING JIE CLEMENT
Ins Policy No. :
Date of Accident : 24/3/2022

Document No. : SQT22000814 Page 3
Date : 25. Mar 2022
Customer No. : WZC008
Svc Advisor : SUHELMI
Engine No : R16B25502374
Date | Time : 25. Mar 2022 11:51:54 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYL.F. <i>one</i>	1	63.20	25	47.40	3.32	50.72
74940-SZW-003	BUZZER ASSYSMART <i>11</i>	1	65.40	25	49.05	3.43	52.48
72841-SA0-315	OIL SHEET <i>one</i>	1 <i>43.40</i>	37.00	25 <i>32.55</i>	27.75	1.94	29.69
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>Sub</i> SVC	1	45.00		45.00	3.15	48.15
Sum Item					5367.76	375.75	5,743.51
BOSUN	SUNDRIES <i>one</i>	1	50.00	20	50.00	3.50	53.50
BOJSE	BODY JOINT SEALANT. <i>one</i>	1	400.00	300	400.00	28.00	428.00
BOBC	BODY UNDERSIDE COATING (N)	1	400.00	300	400.00	28.00	428.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150	180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00	160	200.00	14.00	214.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	420.00	300	420.00	29.40	449.40
BG51D	REMOVE & INSTALL RR. L QTR GLASS.(N)	1	420.00	300	420.00	29.40	449.40
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00	350	450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	325	450.00	31.50	481.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	450.00	325	450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00	320	350.00	24.50	374.50
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	1	350.00	280	350.00	24.50	374.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1 <i>11</i>	450.00	X	450.00	31.50	481.50
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL, ALIGN CHASSIS FR <i>650 x 11</i>	1	9000.00	7150	9000.00	630.00	9630.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) <i>5 20x6.5</i>	1	4000.00	3700	4000.00	280.00	4280.00
Sum Labor					18720.00	1,310.40	20,030.40

Survey By

14530

Printed on 25/3/2022 3:16:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SND7849K
Chassis No : MRHFC5650JT002049
Model : CIVIC 1.6 VTI YM2018
Owner's Name : YAP YING JIE CLEMENT
Ins Policy No. :
Date of Accident : 24/3/2022

Document No. : SQT22000814 **Page** 4
Date : 25. Mar 2022
Customer No. : WZC008
Svc Advisor : SUHELMI
Engine No : R16B25502374
Date | Time : 25. Mar 2022 11:51:54 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	29/3/22 @ 11am.						
Excess							
Status	Not Allowed						
Signature	John Lee (Rep. Party)						

Total Amount 24,087.76 1,686.15 25,773.91
Total (Inclusive of GST) 25,773.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 25/3/2022 3:16:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SND7849K

Chassis No : MRHFC5650JT002049

Model : CIVIC 1.6 VTI YM2018

Owner's Name : YAP YING JIE CLEMENT

Ins Policy No. :

Date of Accident : 24/3/2022

Document No. : SQT22000854 Page 1

Date : 29. Mar 2022

Customer No. : WZC008

Svc Advisor : SUHELMI

Engine No : R16B25502374

Date | Time : 29. Mar 2022 3:30:58 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY ITEM AND LABOUR							
75450-TEA-T02	OUTLET ASSY,RR.AIR <i>Bro</i>	1	9.20	25	6.90	0.48	7.38
73227-TEA-003	RUBBER C/WINDSHIELD DAM <i>ner</i>	1	19.70	25	14.77	1.03	15.80
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>ner</i>	3	10.30	25	23.17	1.62	24.79
91501-S70-003	FASTENER BW/SHIELD <i>ner</i>	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>ner</i>	2	3.80	25	5.70	0.40	6.10
64350-TEA-T00ZZ	SUPPORT COMPR.RR.SHELF <i>ner</i>	1	55.70	25	41.77	2.92	44.69
64750-TEA-T00ZZ	SUPPORT COMPL.RR.SHELF <i>ner</i>	1	55.70	25	41.77	2.92	44.69
65615-TEA-T00ZZ	STIFFENER BR.RR.FLOOR SIDE <i>ner</i>	1	31.10	25	23.32	1.63	24.95
65616-TEA-T00ZZ	FRAMER.RR.FRAME RR.UPPER <i>ner</i>	1	46.70	25	35.02	2.45	37.47
65626-TBA-A00ZZ	GUSSETR.RR.PANEL <i>ner</i>	1	23.60	25	17.70	1.24	18.94
66500-TET-H00ZZ	SHELF COMPRR.PARCEL <i>ner</i>	1	279.10	25	209.32	14.65	223.97
84601-TEA-Q02ZA	LINING ASSY,R.TRUNK <i>ner</i>	1	57.90	25	43.42	3.04	46.46
84651-TEA-Q02ZA	LINING ASSY,L.TRUNK SIDE <i>ner</i>	1	55.50	25	41.62	2.91	44.53
Sum Item					512.43	35.85	548.28
BKRP23B	CUT & RENEW PARCEL SHELF INCLUDING	1	1950.00	<i>975</i>	1950.00	136.50	2086.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	<i>450</i>	650.00	45.50	695.50
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	520.00	<i>an</i>	520.00	36.40	556.40
Sum Labor					3120.00	218.40	3,338.40
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	150.00	<i>ner</i>	150.00	10.50	160.50
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	150.00	<i>ner</i>	150.00	10.50	160.50
Sum Ext. Service					300.00	21.00	321.00

Survey By

Date & Time

Excess

Total Amount 3,932.43 275.25 4,207.68

Total (Inclusive of GST) 4,207.68

Printed on 30/3/2022 9:57:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

30/04/2022

Attn: Marcus

WD: 18 days

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0128237 / CHINA TAIPING
 Chassis No: MRHFC5650JT002049
 License No: SND7849K
 Mileage: 47580
 Engine No: R16B25502374

Document No: SVO22014716
 Printed By: SUHELMI
 Order Date: 29. March 2022
 Order Time: 11:57:39 AM
 Service Advisor: SUHELMI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YAP YING JIE CLEMENT OWNER INSURER: LIBERTY ACC DATE: 24/03/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: XE5948Y						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	41.60	25	31.20	2.18	33.38
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	8.90	25	6.67	0.47	7.14
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE	1	8.90	25	6.67	0.47	7.14
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.60	25	1.95	0.14	2.09
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.60	25	1.95	0.14	2.09
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TEC-307ZZ	PANEL SETRR.	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	247.30	25	185.47	12.98	198.45
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	812.30	25	609.22	42.65	651.87
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	1	812.30	25	609.22	42.65	651.87
63321-TEA-T00ZZ	GUTTERR.RR.UPPER	1	33.50	25	25.12	1.76	26.88
63721-TEA-T00ZZ	GUTTERL.RR.UPPER	1	33.50	25	25.12	1.76	26.88
63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT	1	69.30	25	51.97	3.64	55.61
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT	1	69.30	25	51.97	3.64	55.61
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	114.80	25	86.10	6.03	92.13
75701-TBA-A10	EMBLEM,H-MARK	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.22	3.37
74851-TEA-003	LOCK ASSYTRUNK	1	84.90	25	63.67	4.46	68.13
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	37.60	25	28.20	1.97	30.17
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	51.10	25	38.32	2.68	41.00
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	51.10	25	38.32	2.68	41.00
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
73500-TEA-T02	GLASS ASSYR.QUARTER WINDSHIELD	1	155.90	25	116.92	8.18	125.10
73550-TEA-T02	GLASS ASSY.,L.QUARTER WINDSHIELD	1	155.90	25	116.92	8.18	125.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
33500-TEA-T01	TAILLIGHT ASSYR.	1	298.40	25	223.80	15.67	239.47
33550-TEA-T01	TAILLIGHT ASSYL.	1	321.10	25	240.82	16.86	257.68
34150-TEX-Y01	LIGHT ASSYR.LID	1	139.60	25	104.70	7.33	112.03
34155-TEX-Y01	LIGHT ASSYL.LID	1	139.60	25	104.70	7.33	112.03
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	2	155.40	25	233.10	16.32	249.42



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0128237 / CHINA TAIPING
Chassis No: MRHFC5650JT002049
License No: SND7849K
Mileage: 47580
Engine No: R16B25502374

Document No: SVO22014716
Printed By: SUHELMI
Order Date: 29. March 2022
Order Time: 11:57:39 AM
Service Advisor: SUHELMI

32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	32.10	25	24.07	1.68	25.75
38387-TZ5-A01	ANTENNA ASSYL.F.	1	63.20	25	47.40	3.32	50.72
72841-SH3-315	OILSHEET	1	43.40	25	32.55	2.28	34.83
75450-TEA-T02	OUTLET ASSY,RR.AIR (S)	1	9.20	25	6.90	0.48	7.38
73227-TEA-003	RUBBER CWINDOWSHIELD DAM (S)	1	19.70	25	14.77	1.03	15.80
73525-SYY-000	RUBBERRR QTR W/SHIELD (S)	3	10.30	25	23.17	1.62	24.79
91501-S70-003	FASTENER BW/SHIELD (S)	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD (S)	2	3.80	25	5.70	0.40	6.10
64350-TEA-T00ZZ	SUPPORT COMPR.RR.SHELF (S)	1	55.70	25	41.77	2.92	44.69
64750-TEA-T00ZZ	SUPPORT COMPL.RR.SHELF (S)	1	55.70	25	41.77	2.92	44.69
65615-TEA-T00ZZ	STIFFENER BR.RR.FLOOR SIDE (S)	1	31.10	25	23.32	1.63	24.95
65616-TEA-T00ZZ	FRAMER.RR.FRAME RR.UPPER (S)	1	46.70	25	35.02	2.45	37.47
65626-TBA-A00ZZ	GUSSETR.RR.PANEL (S)	1	23.60	25	17.70	1.24	18.94
66500-TET-H00ZZ	SHELF COMPRR.PARCEL (S)	1	279.10	25	209.32	14.65	223.97
84601-TEA-Q02ZA	LINING ASSY,R.TRUNK (S)	1	57.90	25	43.42	3.04	46.46
84651-TEA-Q02ZA	LINING ASSY,L.TRUNK SIDE (S)	1	55.50	25	41.62	2.91	44.53
SUM PARTS:					5,165.08	361.55	5,526.63
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOJSE	0760	1	300.00		300.00	21.00	321.00
	BODY JOINT SEALANT.						
BOBC	0760	1	300.00		300.00	21.00	321.00
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	250.00		250.00	17.50	267.50
	APPLY BODY UNDERSIDE COATING (N).						
BML02I	EXT-YJ	1	150.00		150.00	10.50	160.50
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BA02R	EXT-YJ	1	160.00		160.00	11.20	171.20
	REMOVE & INSTALL REVERSE						
	SENSORS-4 PCS (N)						
BC011R	0760	1	350.00		350.00	24.50	374.50
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BC012R	0760	1	350.00		350.00	24.50	374.50
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BG52D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. R QTR GLASS.						
	(N)						
BG51D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. L QTR GLASS.						
	(N)						
BKTRR	EXT-YJ	1	350.00		350.00	24.50	374.50
	REMOVE & TRANSFER ITEMS TO NEW						
	TRUNK LID						
	ADJUST & ALIGN.						
BMI03D	EXT-YJ	1	325.00		325.00	22.75	347.75
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS						
	GARNISHES.(N)						
BMI02D	EXT-YJ	1	325.00		325.00	22.75	347.75
	REMOVE & INSTALL SPEAKER BOARD						
	RR SEATS TRUNK						
	LININGS GARNISHES & ETC.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0128237 / CHINA TAIPIING
Chassis No: MRHFC5650JT002049
License No: SND7849K
Mileage: 47580
Engine No: R16B25502374

Document No: SVO22014716
Printed By: SUHELMI
Order Date: 29. March 2022
Order Time: 11:57:39 AM
Service Advisor: SUHELMI

BMF00D	EXT-YJ RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	320.00	320.00	22.40	342.40
BMU30R	EXT-YJ REMOVE & INSTALL EXHAUST SYSTEM. (N)	1	280.00	280.00	19.60	299.60
BKRP21B	EXT-YJ CUT OFF & RENEW RR FLOOR PANEL, ALIGN CHASSIS FR & FENDERS. STRAIGHTEN MAIN FRAME INCLUDING FITTING	1	7,150.00	7,150.00	500.50	7,650.50
BP07R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)	1	3,700.00	3,700.00	259.00	3,959.00
BKRP23B	EXT-YJ CUT & RENEW PARCEL SHELF (S) INCLUDING FITTING ON ATTACHMENT ITEM.	1	975.00	975.00	68.25	1,043.25
BG02D	EXT-YJ (S) REMOVE & INSTALL RR. WINDSCREEN. (N)	1	450.00	450.00	31.50	481.50
			SUM LABOUR:	16,355.00	1,144.85	17,499.85
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON (S) REAR QTR GLASS.	1	150.00	150.00	10.50	160.50
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON (S) REAR QTR GLASS.	1	150.00	150.00	10.50	160.50
			SUM EXT SERVICE:	300.00	21.00	321.00
			TOTAL SGD	21,820.08	1,527.40	23,347.48
			Total Payable (SGD)			23,347.48

GST Amount is calculated from individual line(s)