



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22002890/Uty3e2	
			Date: 27/04/2022	
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 4264C	Veh. Inspected	SMK 9322A
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10014434/KY	Excess (\$)	0.00
	Assign From	SHAFAWATI MD RABU	Assign Date	29/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180K (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WDD2040452A321665	Colour	BLACK
	Odometer	208384 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50Z R17	NEXEN	6 mm
	L/H Front Tyre	225/50Z R17	NEXEN	6 mm
	R/H Rear Tyre	225/50Z R17	NEXEN	6 mm
	L/H Rear Tyre	225/50Z R17	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/03/2022	Inspection Date	29/03/2022
	Survey held at	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre		
	Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	