



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002895/Uty3n2 Date: 09/05/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SND 9151B	Veh. Inspected	SJD 1831Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2201024/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	29/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF16308S219729	Colour	WHITE	
Odometer	212671 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 ZR17	KUMHO	6 mm	
L/H Front Tyre	225/45 ZR17	KUMHO	6 mm	
R/H Rear Tyre	225/45 ZR17	KUMHO	6 mm	
L/H Rear Tyre	225/45 ZR17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2022	Inspection Date	29/03/2022	
Survey held at	1 KAKI BUKIT AVE 6 #01-22 AUTOBAY @ KAKI BUKIT			
Repairer	SPRAYSMITHS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	