

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2202149

64 CECIL STREET INV Date 13/04/2022

#05-02 IOB BUILDING Reference CS3/GRB22002896/Gqy3e2 SINGAPORE 049711

Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SMX 4056H

Insured Veh. SMV 9278L

Claim No. MFL2022D0001343

Policy No. D21MFL0000447_01

Accident Date 19/03/2022

Inspection Date 04/04/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 04.04.2022 03.40pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM