



Your Ref : 21/22/22/VP05/025468

Date: 16<sup>th</sup> Apr 2022

Our Ref : CS/LPC22002901/Uqy3e2

**M/s Lonpac Insurance Bhd**

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBR 9055P  
INSURED VEHICLE: SKP 6911S  
ACCIDENT ON 15/02/2022**

Instruction was received to inspect the vehicle Reg. No. FBR 9055P. The inspection was conducted on 29/03/2022 at the premises of M/s Erofia Motor Trading Pte Ltd, 1 Kaki Bukit Avenue 6 #02-62, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: FBR 9055P
Make/Model	: Yamaha FZS ABS Manual
Year of Registration	: 2020
Body Colour	: Black
Chassis Number	: ME1RG6623L0037916
Engine Capacity	: 149 cc
Speedometer Reading	: Nil

The vehicle sustained damages at the front portion and o/s body. The chassis frame and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 11,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 6,328.00)
Nett Liability	<u>S\$ 4,672.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.