

(08/11/13) wef

ASS. REC. BY: Form

REF:

CS/CT12200291/Rg43

886T

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SMN 2755P

Yr Regn:

2019 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 2755P

at Workshop m/s Auto Insure

of 6, MARILYN LN. 1

Insured:

CTI

Policy No.

Claims No. SNM22D201864/C01

Sum Insured:


Excess: 1000 / 500 (1000)

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

265K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Eng/No:

C/No:

WP122295ZKL B04529

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/40R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

16/03/22

D.O.I.

31/03/22

Survey held at

Auto Insure

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 156K

12/04/22@5.45pm revert to Tan Kah Leong via Merimen.

05/05/22@5.36pm Albert Chua informed C/A via Merimen.

09/05/22@10.56am Informed wksp C/A & ex:\$1000 by email.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

to Insure Pte. Ltd
Marsiling Lane
739145



Insurer Reference: SMN2755P
Repairer Reference: M4524/SMN2755P
Date calculated: 26/03/2022 2:51 PM

Full Report
Registration: SMN2755P
Printed: 26/03/2022 2:51 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Marvyn Chua	Currency:	SGD
Claim Reference:	SMN2755P	Date of Incident:	16/03/22
Estimated Repair Time:	23	Hire Car Start:	
Actual Repair Days:	23	Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PORSCHE
Model:	MACAN
Sub Model:	BASE MODEL
Model Sheet Number:	04 10 01
Registration:	SMN2755P
VIN number:	WP1ZZZ95ZKLB04529
Odometer:	22179

Model Specs

FR PRODUCTION START	EMISSION STD EURO 6+	COMPASS	3 ZONE AUTO AIR CON
W-SCREEN HEAT ABSORB	TAILGATE POWER LOCK	DOOR MIRROR	D/MIRROR WITH MEMORY
VOICE CONTROL SYSTEM	SOUND SYSTEM	ENTRY & DRIVE	ANTI THEFT ALARM
TELEPHONE COMF RSAP	PARKING AID/CAMERA	STOP-START SYSTEM	INSTR PNL NAT LEATHE
SMOKER PACKAGE	IN TRIM NATUR LEATH	S/CVR NATURAL LEATH	OUT/IN MIRR AUTO DIM
LANE CHANGING ASSIST	GT ST WHEEL LEAT HEA	INTERIOR LAMP PACK	1984CCM 185KW
TOW BAR PREPARATION	7-SPEED AUTOMATIK	REAR BRAKE 17 INCH	FRONT BRAKE 17 INCH
PASM SUSPENSION	CRUISE CONTROL	TYRE PRESSURE SENSOR	265/45 - 295/40 R20
9/10J X 20 ALLOY	WHEEL COVER CONCAVE	SIDE MLDG PAINTING	TYRE INFLATING SYS
EXTERIOR BLACK GLOSS	HEAD AIRBAG	EXH PIPE ORNAMENTAL	SILL TRIM BLACK
TWO COAT METALLIC			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
51 92 19 01	R + R L/ENGINE COMPARTMENT INSULATION		4.0	16.80
51 92 19 02	R + R R/ENGINE COMPARTMENT INSULATION		4.0	16.80
63 15 19 00	REMOVE AND REFIT FRONT BUMPER TRIM		13.3	55.86
	INCLUDES: BONNET LOCK TRIM			
	AND FRONT LOWER TRIM REMOVE AND REFIT			
63 15 55 50	RENEW FRONT PANEL		21.1	88.62
	(REMOVED)			
	INCLUDES: R + R AIR VENT GRILLE, NUMBER			
	PLATE BRACKET AND AIR INLET COVER FRAME			
69 70 19 50	R + R FRONT BUMPER LOWER CROSSMEMBER		2.3	9.66
63 10 19 50	REMOVE AND REFIT FRONT BUMPER CARRIER		2.6	10.92
	(FRONT BUMPER REMOVED)			
63 33 19 51	R + R L/F BUMPER MOUNTING		2.0	8.40
63 33 19 52	R + R R/F BUMPER MOUNTING		2.0	8.40
50 55 19 01)	L/F LOWER WING REMOVE AND REFIT		6.5	27.30
	(FRONT WATER BOX COVER REMOVED)			
	INCLUDES: L/F WHEELHOUSE COVER AND			
	R + R WASHER RESERVOIR			

	Description	WU	Price SGD
NO NUMBER	REMOVE AND REFIT L/F UPPER WING	12.0	50.40
55 19 02)	R/F LOWER WING REMOVE AND REFIT (FRONT WATER BOX COVER REMOVED) INCLUDES: R/F WHEELHOUSE COVER AND ADDITIONAL HEATER R + R	9.8	41.16
NO NUMBER	REMOVE AND REFIT R/F UPPER WING	11.4	47.88
63 17 19 51	R + R L/UPPER HEADLAMP COVER	1.0	4.20
63 17 19 52	R + R R/UPPER HEADLAMP COVER	1.0	4.20
69 53 19 50	R + R AIRBAG CONTROL UNIT	1.3	5.46
69 53 55 00)	RENEW AIRBAG CONTROL UNIT	10.6	44.52
94 15 19 51	R + R LEFT HEADLAMP	1.2	5.04
94 15 55 01)	RENEW L/HEADLAMP (REMOVED)	0.6	2.52
94 15 19 52	R + R RIGHT HEADLAMP	1.2	5.04
94 15 55 02)	RENEW R/HEADLAMP (REMOVED)	0.6	2.52
94 15 16 50	ADJUST HEADLAMPS	1.5	6.30
50 38 19 50)	R + R FRONT LOCK CARRIER	2.9	12.18
50 38 55 50	RENEW FRONT LOCK CARRIER (LOCK CARRIER PANEL REMOVED) INCLUDES: BRACKET SUPPORT HEADLAMP REMOVE AND REFIT	0.6	2.52
10 83 19 50	R + R ENGINE COVER	0.4	1.68
55 22 19 00	R + R BONNET INCLUDES: R + R WASHER JETS, ADJUST BONNET	16.3	68.46
55 22 55 50	RENEW BONNET (REMOVED)	17.4	73.08
55 25 19 51)	R + R L/BONNET HINGE	0.4	1.68
55 25 19 52)	R + R R/BONNET HINGE	0.4	1.68
55 14 19 50	R + R BONNET CABLE	0.8	3.36
NO NUMBER	R + R L/BASE PLATE	1.0	4.20
NO NUMBER	R + R R/BASE PLATE	1.0	4.20
50 87 19 00	R + R COWL PANEL COVER	2.9	12.18
92 25 20 00	R + R WIPER ARMS INCLUDES: WIPER BLADES	4.8	20.16
50 38 19 51)	R + R L/CHARGE AIR COOLER BRACKET	3.8	15.96
50 38 19 52)	R + R R/CHARGE AIR COOLER BRACKET	2.2	9.24
NO NUMBER	R + R L/LOCK CARRIER STRUT	2.0	8.40
NO NUMBER	R + R R/LOCK CARRIER STRUT	2.0	8.40
55 22 51 50	FRONT SEAL COVER	5.0	21.00
55 14 19 55	R + R REAR BONNET BOWDEN CABLE	3.3	13.86
50 60 55 01	RENEW L/HEADLAMP BRACKET	45.7	191.94
50 38 55 01)	RENEW L/INTERCOOLER BRACKET	1.7	7.14
50 38 55 02)	RENEW R/INTERCOOLER BRACKET	1.7	7.14
50 60 55 02	RENEW R/HEADLAMP BRACKET	45.7	191.94
50 79 55 53	RENEW L/F SIDEMEMBER REINFORCEMENT FRONT	45.6	191.52
50 79 55 54	RENEW R/F SIDEMEMBER REINFORCEMENT FRONT	45.5	191.10
70 84 19 00)	R + R ROOF LINING (A PILLAR TRIMS REMOVED) INCLUDES: SUN VISORS, HANDLES AND R + R B-/C-/D-PILLAR TRIMS	28.2	118.44
69 66 19 01)	R + R L/HEAD AIRBAG	1.1	4.62
69 66 19 02)	R + R R/HEAD AIRBAG	1.1	4.62
66 61 19 01	R + R WINDSCREEN LEFT MOULDING FRAME	2.2	9.24
66 61 19 02	R + R WINDSCREEN RIGHT MOULDING FRAME	2.2	9.24
70 57 20 00)	R + R BOTH UPPER A-PILLAR TRIMS	0.5	2.10

Description

WU Price SGD

11 19 51)	R + R L/FRT SEAT BELT	1.7	7.14
11 19 52)	R + R R/FRT SEAT BELT	1.7	7.14
03 19 11	R + R L/BOOT TRIM	1.8	7.56
03 19 12	R + R R/BOOT TRIM	1.9	7.98
39 19 05	R + R REAR LOCK CARRIER COVER	2.7	11.34
18 19 00	R + R INSTRUMENT PANEL	33.8	141.96
18 55 50	RENEW INSTRUMENT PANEL (REMOVED)	1.2	5.04
17 19 00	R + R ENGINE TUNNEL CONSOLE	7.9	33.18
24 19 00	R + R REAR SEAT	3.7	15.54
12 19 51)	R + R L/R SEAT BELT	0.5	2.10
12 19 52)	R + R R/R SEAT BELT	0.5	2.10
24 25 19 90	R + R AIR CLEANER	1.3	5.46
NO NUMBER	R + R LEFT RADIATOR AIR GUIDE	1.0	4.20
NO NUMBER	R + R RIGHT RADIATOR AIR GUIDE	1.0	4.20
NO NUMBER	R + R ENGINE RADIATOR AIR GUIDE	1.0	4.20
19 24 19 90	R + R RADIATOR AIR GUIDE	1.2	5.04
NO NUMBER	R + R FRONT AIR GUIDE	1.5	6.30
19 24 19 95)	REMOVE AND REFIT REAR AIR GUIDE	0.7	2.94
87 50 19 90	R + R CONDENSER	18.0	75.60
87 50 55 50	CONDENSER RENEW (REMOVED))	0.6	2.52
21 39 19 41)	R + R LOWER CHARGE AIR COOLING PIPE	5.3	22.26
21 43 19 90	R + R AIR INTERCOOLER	3.2	13.44
21 43 19 12)	R + R R/CHARGE AIR COOLER	1.9	7.98
NO NUMBER	R + R OIL TUBE	3.0	12.60
19 70 19 90)	R + R RADIATOR	3.4	14.28
19 70 55 50	RENEW RADIATOR (REMOVED)	0.8	3.36
19 20 19 90)	R + R ELECTRIC FAN	0.6	2.52
NO NUMBER	R + R ELECTRIC FAN OR ATTACHED PARTS	3.0	12.60
NO NUMBER	R + R UPPER COOLANT HOSE	1.0	4.20
NO NUMBER	R + R LOWER COOLANT HOSE	1.0	4.20
19 38 17 50	DRAIN + REFILL COOLANT	5.4	22.68
27 22 19 90	R + R ALTERNATOR	3.0	12.60
44 05 19 02	R + R RIGHT FRONT WHEEL	3.5	14.70
44 40 19 52	R + R RIGHT FRONT TYRE	2.9	12.18
	(WHEEL REMOVED)		
	INCLUDES: BALANCE WHEEL AND LEAKAGE TEST		
44 05 19 04	R + R RIGHT REAR WHEEL	3.5	14.70
44 40 19 54	R + R RIGHT REAR TYRE	2.9	12.18
	(WHEEL REMOVED)		
	INCLUDES: BALANCE WHEEL AND LEAKAGE TEST		
37 02 35 50	REFILL GEARBOX OIL	3.9	16.38
87 03 17 50	DRAIN AND REFILL AIR CONDITIONING	7.5	31.50
	REFRIGERANT		
	INCLUDES: CHECK WITH LEAK DETECTOR,		
	CHECK AIR CONDITIONING COOLING		
1481	LEFT FRONT DOOR REPAIR	20.0*	84.00
1482	RIGHT FRONT DOOR REPAIR	20.0*	84.00

Labour Cost

Hrs

WU

Panel / Mechanical Labour

57.80

577.9

2,427.18

Total of Labour

2,427.18

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRT BUMPER LWR C-MEM NEW PART PAINTING		6.0	
	BONNET NEW PART PAINTING		38.0	
	L/F LOWER WING NEW PART PAINTING		9.0	
	R/F LOWER WING NEW PART PAINTING		9.0	
	L/F UPPER WING NEW PART PAINTING		8.0	
	R/F UPPER WING NEW PART PAINTING		8.0	
	L/F SIDE MEMBER SUPP SURFACE PAINT		4.0	
	R/F SIDE MEMBER SUPP SURFACE PAINT		4.0	
	L/HEADLAMP MOUNTING SURFACE PAINT		4.0	
	R/HEADLAMP MOUNTING SURFACE PAINT		4.0	
	L/F S-MEMBER SECTION SURFACE PAINT		4.0	
	R/F S-MEMBER SECTION SURFACE PAINT		4.0	
	FRONT BUMPER NEW PART PAINT K1R		9.0	
	FRONT BUMPER CAP NEW PART PAINT K1R		3.0	
	LEFT FRONT DOOR REPAIR PAINTING >50%		27.0	
	RIGHT FRONT DOOR REPAIR PAINTING >50%		27.0	

Paint Material Per Part

Code	Description	Price SGD
0345	FRT BUMPER LWR C-MEM NEW PART PAINTING	1.55
0471	BONNET NEW PART PAINTING	138.80
0741	L/F LOWER WING NEW PART PAINTING	16.00
0742	R/F LOWER WING NEW PART PAINTING	16.00
0745	L/F UPPER WING NEW PART PAINTING	9.80
0746	R/F UPPER WING NEW PART PAINTING	9.80
1167	L/F SIDE MEMBER SUPP SURFACE PAINT	2.49
1168	R/F SIDE MEMBER SUPP SURFACE PAINT	2.49
1169	L/HEADLAMP MOUNTING SURFACE PAINT	2.49
1170	R/HEADLAMP MOUNTING SURFACE PAINT	2.49
1287	L/F S-MEMBER SECTION SURFACE PAINT	2.49
1288	R/F S-MEMBER SECTION SURFACE PAINT	2.49
0283	FRONT BUMPER NEW PART PAINT K1R	40.34
0293	FRONT BUMPER CAP NEW PART PAINT K1R	0.49
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	38.32
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	38.32

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	42.00 SGD/h		168.0	
	Time Paint			
	Preparation Main Work Metal	2.10	21.0	88.20
	Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	19.40	194.0	814.80

Material Cost - Paint

New Part Painting	Price SGD
New Part Painting - Plastic K1R	191.95
Repair Painting	40.83
Surface-/Blend Paint	76.64
Material-constant Metal	14.94
Material-constant Plastic	18.10
Total	9.00
	351.46

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Part Source	Price SGD
7441	ACT/ AIRBAG CONTROL UNIT	95B 959 655G	Original	2,160.00
8391	AIR FILTER ASSY	95B 129 601F	Original	700.00
7745	di/ AIR GUIDE GRILLE	95B 121 257FY	Original	480.00
8411	ALTERNATOR	PAC 903 024A	Original	3,360.00
0471	bt/ BONNET	95B 823 031LYGRV	Original	3,600.00
0481	di/ BONNET INSULATION	95B 863 831C	Original	360.00
0933	? BONNET LOCK COVER	95B 805 806P 1E0	Original	120.00
0500	? BONNET REL CABLE	95B 823 535	Original	110.00
0504	? BONNET RELEASE	95B 823 661A	Original	40.00
	HANDL			
0490	nu/ BONNET SEAL	95B 823 739	Original	50.00
0637	cm/ COMP L/PARK LAMP/IND	95B 953 081B	Original	840.00
0638	? COMP R/PARK LAMP/IND	95B 953 082B	Original	840.00
4465	bt/ CONDENSER	9A7 260 40301	Original	1,920.00
8729	bt/ COOLER PRESSURE PIPE	95B 145 673D	Original	960.00
7445	ACT/ DRIVER AIRBAG	95B 880 201BPA34	Original	4,320.00
8237	? ENGINE COVER	95B 103 925N	Original	840.00
8771	? ENGINE INSULATION	95B 863 821D	Original	540.00
7790	? FAN HOUSING	8K0 121 207A	Original	540.00
0401	cm/ FR BUMP LWR GRILL CV	95B 805 647A 1E0	Original	480.00
0404	? FR LWR BUMPER GRILLE	95B 805 935 1E0	Original	600.00
0499	? FRONT BOWDEN CABLE	95B 823 531B	Original	300.00
0502	? FRONT BOWDEN CABLE	95B 823 529B	Original	75.00
0283	TRAN/ FRONT BUMPER	95B 807 221K G2X	Original	2,640.00
0293	mu/ FRONT BUMPER CAP	95B 807 156C G2X	Original	170.00
0402	? FRONT LWR AIR GRILLE	95B 805 187 1E0	Original	420.00
0431	mu/ FRONT MANUFACT	991 559 21100	Original	580.00
	BADGE			
0391	? FRONT SPOILER	95B 807 061M 1E0	Original	720.00
0347	? FRT BUMPER FILLING	95B 807 550R	Original	170.00
0345	? FRT BUMPER LWR C-MEM	95B 805 241E	Original	700.00
0340	nu/ FRT BUMPER SUPPORT	8R0 807 113D	Original	675.00
0513	? FRT COVER LOCK SEAL	95B 129 551	Original	170.00
7733	? FRT LOWER AIR GUIDE	95B 121 291	Original	265.00
0258	cm/ FRT NO PLATE REINF	95B 807 287Q 1E0	Original	255.00
0929	bt/ FRT UPP LOCK CARRIER	95B 805 931F	Original	660.00
7741	? FT COOL FAN AIR DUCT	95B 121 710 1E0	Original	265.00
0410	cm/ GRILLE	95B 807 683AN1E0	Original	840.00
4957	di/ HEADLINING	95B 867 501HM6F2	Original	6,960.00
9650	? HIGH TONE HORN	95B 951 212H	Original	265.00
7768	? INLET OIL PRESS PIPE	95B 317 818D	Original	480.00
4331	? INSTRUMENT PANEL	95B 857 003BB6J0	Original	9,360.00
8745	? INTERCOOLER	PAB 145 805	Original	2,640.00
8739	? INT MANIF PRESS HOSE	8R0 145 993C	Original	480.00

	Description	Part Number	Part Source	Price SGD
1	L/AIR COOLER BRACKET	95B 805 295D	Original	660.00
45	L/BLOWER LOCK RING	PAB 941 749	Original	120.00
495	L/BONNET LOCK	95B 823 509A	Original	180.00
8211	L/ENG COM INSULATION	95B 825 101G 1E0	Original	180.00
4605	L/F AIRBAG SENSOR	2H0 959 652	Original	240.00
7785	L/FAN	9A7 959 45516	Original	1,680.00
0477	L/F BASE PLATE	7N0 843 637B	Original	110.00
0531	L/F BONNET STOP	95B 823 429	Original	60.00
0497	L/F BONNET STRUT	95B 823 359	Original	160.00
0291	L/F BUMPER AIR GUIDE	95B 121 333C 1E0	Original	160.00
0321	L/F BUMPER MOUNTING	8R0 807 133A	Original	240.00
0303	L/F CENTRE SENSOR	5Q0 919 275B G2X	Original	580.00
0937	L/F H-LAMP FRT CVR	95B 807 173C 1E0	Original	168.00
0555	L/F H-LAMP REAR CVR	95B 941 617A	Original	110.00
0557	L/F H-LAMP REAR HARN	95B 941 559C	Original	100.00
0493	L/F LOCK HOOK CVR	95B 823 259B	Original	110.00
0741	L/F LOWER WING	95B 821	Original	1,500.00
		101DYGRV		
0369	L/F LWR BUMPER TRIM	95B 807 823A 1E0	Original	100.00
0359	L/F OUT BUMPER BRKT	95B 807 165	Original	110.00
0297	L/F OUT BUMP GRILLE	95B 807 681H 1E0	Original	145.00
0301	L/F OUTER SENSOR	5Q0 919 275C G2X	Original	265.00
4661	L/F SEAT BELT	95B 857 705C HCP	Original	1,060.00
1167	L/F SIDE MEMBER SUPP	95B 805 831AYGRV	Original	110.00
1287	L/F S-MEMBER SECTION	95B 803 101AYGRV	Original	700.00
0479	L/F SUPPORT BRACKET	7N0 843 841C	Original	85.00
0745	L/F UPPER WING	95B 821 103CYGRV	Original	600.00
1415	L/F WATER DEFLECTOR	95B 845 327 1E0	Original	70.00
0841	L/F WHEELHOUSE	95B 809 961D	Original	780.00
	COVER			
0751	L/F WING BRACKET RR	95B 809 573BYGRV	Original	120.00
0749	L/F WING COVER	95B 854 777B 1E0	Original	170.00
0367	L/GRILLE SIDE MLDG	95B 807 819B 1E0	Original	180.00
4631	L/HEAD AIRBAG	95B 880 741A	Original	2,100.00
0547	L/HEADLAMP INN FAN	95B 941 052	Original	240.00
0631	L/HEADLAMP MOUNTING	95B 941 121F	Original	115.00
1169	L/HEADLAMP MOUNTING	95B 805 475AYGRV	Original	600.00
0939	L/HEADLAMP SEAL	95B 941 323K	Original	135.00
7774	L/INLET HOSE	95B 121 109F	Original	240.00
0931	L/LOCK CARRIER SUPP	95B 807 333	Original	145.00
7769	L/LWR RADIATOR BRKT	95B 121 093	Original	50.00
7809	L/LWR RAD RUBB	4H0 121 268A	Original	115.00
	MOUNT			
0767	L/OUT GUIDE PART	95B 823 417	Original	60.00
7735	L/RADIATOR AIR GUIDE	95B 121 673C 1E0	Original	90.00
7807	L/RADIATOR RUBB MNTG	8K0 121 276A	Original	40.00
0989	L/RETAINER RAIL	95B 807 889F	Original	120.00
7822	L/R LWR RAD HOSE	95B 121 056E	Original	120.00
7737	L/R RAD AIR GUIDE	95B 121 699G 1E0	Original	100.00
4841	L/R SEAT BELT	95B 857 805B HCP	Original	660.00
0363	L/UPP GRILLE MLDG	95B 807 685B 1E0	Original	100.00
7811	L/UPP RAD RUBB MOUNT	8K0 121 275C	Original	30.00
1417	L/WINDSCREEN MLDG	95B 845 453	Original	70.00
0617	LEFT ADJUSTER	PAF 007 581	Original	70.00
0475	LEFT BONNET HINGE	95B 823 301E	Original	170.00
0535	LEFT BONNET STOP	95B 845 471	Original	100.00

	Description	Part Number	Part Source	Price SGD
1	LEFT HEADLAMP ASSY	95B 941 079AM	Original	3,600.00
5	LEFT PRESSURE HOSE	95B 145 709A	Original	660.00
32	LOAD ROOM SEAT PAD	991 559 21502	Original	30.00
649	LOW TONE HORN	95B 951 211K	Original	170.00
767	OIL PRESSURE PIPE	95B 317 817D	Original	410.00
4325	PASSENGER AIRBAG	95B 880 204B	Original	4,800.00
7764	PRESSURE OIL PIPE	95B 317 826E	Original	480.00
1022	R/AIR COOLER BRACKET	95B 805 594E	Original	460.00
0546	R/BLOWER LOCK RING	PAB 941 749	Original	70.00
0496	R/BONNET LOCK	95B 823 509A	Original	240.00
8212	R/ENG COM INSULATION	95B 825 102G 1E0	Original	240.00
4606	R/F AIRBAG SENSOR	2H0 959 652	Original	420.00
7786	R/FAN	9A7 959 45517	Original	2,340.00
0478	R/F BASE PLATE	7N0 843 638	Original	120.00
0532	R/F BONNET STOP	95B 823 429	Original	110.00
0498	R/F BONNET STRUT	95B 823 359	Original	205.00
0292	R/F BUMPER AIR GUIDE	95B 121 334C 1E0	Original	280.00
0322	R/F BUMPER MOUNTING	8R0 807 134D	Original	265.00
0304	R/F CENTRE SENSOR	5Q0 919 275B G2X	Original	265.00
0938	R/F H-LAMP FRT CVR	95B 807 174C 1E0	Original	145.00
0556	R/F H-LAMP REAR CVR	95B 941 618A	Original	110.00
0558	R/F H-LAMP REAR HARN	95B 941 560C	Original	90.00
0494	R/F LOCK HOOK CVR	95B 823 260B	Original	85.00
0742	R/F LOWER WING	95B 821	Original	1,020.00
		102DYGRV		
0370	R/F LWR BUMPER TRIM	95B 807 824A 1E0	Original	120.00
0360	R/F OUT BUMPER BRKT	95B 807 166	Original	120.00
0298	R/F OUT BUMP GRILLE	95B 807 682H 1E0	Original	120.00
0302	R/F OUTER SENSOR	5Q0 919 275C G2X	Original	265.00
7202	R/FR WHEEL	95B 601 025DG041	Original	3,840.00
4662	R/F SEAT BELT	95B 857 706B HCP	Original	660.00
1168	R/F SIDE MEMBER SUPP	95B 805 832AYGRV	Original	90.00
1288	R/F S-MEMBER SECTION	95B 803 102AYGRV	Original	960.00
0480	R/F SUPPORT BRACKET	7N0 843 842A	Original	110.00
0746	R/F UPPER WING	95B 821 104BYGRV	Original	480.00
1416	R/F WATER DEFLECTOR	95B 845 328 1E0	Original	60.00
0842	R/F WHEELHOUSE	95B 809 962D	Original	360.00
	COVER			
0368	R/GRILLE SIDE MLDG	95B 807 820B 1E0	Original	120.00
4632	R/HEAD AIRBAG	95B 880 742A	Original	2,340.00
0548	R/HEADLAMP INN FAN	95B 941 052	Original	300.00
0632	R/HEADLAMP MOUNTING	95B 941 122F	Original	120.00
1170	R/HEADLAMP MOUNTING	95B 805 476AYGRV	Original	660.00
0940	R/HEADLAMP SEAL	95B 941 324K	Original	145.00
0932	R/LOCK CARRIER SUPP	95B 807 334	Original	145.00
7770	R/LWR RADIATOR BRKT	95B 121 093	Original	50.00
7810	R/LWR RAD RUBB	4H0 121 268A	Original	100.00
	MOUNT			
7736	R/RADIATOR AIR GUIDE	95B 121 674C 1E0	Original	90.00
7808	R/RADIATOR RUBB	8K0 121 276A	Original	40.00
	MNTG			
0990	R/RETAINER RAIL	95B 807 890F	Original	135.00
7738	R/R RAD AIR GUIDE	95B 121 700F 1E0	Original	110.00
9552	R/RR WHEEL	95B 601 025DH041	Original	3,840.00
4842	R/R SEAT BELT	95B 857 805B HCP	Original	780.00
0364	R/UPP GRILLE MLDG	95B 807 686B 1E0	Original	90.00

	Description	Part Number	Part Source	Price SGD
	R/UPP RAD RUBB MOUNT	8K0 121 275C	Original	25.00
X2	R/WATER HOSE	95B 121 109H	Original	340.00
X	R/WINDSCREEN MLDG	95B 845 454	Original	75.00
	RADIATOR	9A7 121 25110	Original	2,880.00
	RADIATOR INTAKE HOSE	95B 122 101A	Original	210.00
	REAR BOWDEN CABLE	95B 823 536A	Original	80.00
X	RIGHT ADJUSTER	PAF 007 581	Original	1,020.00
51	RIGHT BONNET HINGE	95B 823 302E	Original	180.00
N	RIGHT BONNET STOP	95B 845 471	Original	75.00
CA	RIGHT HEADLAMP ASSY	95B 941 080AM	Original	3,600.00
X	RIGHT PRESSURE HOSE	95B 145 790A	Original	660.00
X	RR COOL FAN AIR DUCT	95B 121 707G	Original	300.00
	SPOILER CARRIER	95B 805 842 1E0	Original	410.00
	STRG WHEEL SLIP RING	95B 953 568F	Original	840.00
	UPPER/OIL PRESS PIPE	95B 317 825E	Original	264.00
	V-BELT	06L 903 137A	Original	160.00
	VENT CHANNEL MOTOR	95B 965 501AA	Original	480.00
				0.00
Savings Subtotal				112,737.00
Total				112,737.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	BUMPER CLIPS FRONT	30 50.00*
1001	RADIATOR COOLANT FRONT	30.00*
1002	AIRCON GAS FRONT	40 60.00*
Total Extras		140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Ap 90010068
9 days
P/P
31/03/22 @ 1225
Reket
Excess: 1000 (500) waived
Resay before paint

Cost Calculation

	SGD	SGD
Parts		
Total Parts	112,737.00	112,737.00
Labour Time Base 10 WU/h		
Total 577.9 WU X 42.00 SGD/h		
Total of Labour	2,427.18	2,427.18
Total Of Extras		140.00
Paint Work Time Base 10 WU/h		
Labour Cost 194.0 WU X 42.00 SGD/h	814.80	
Material Cost	351.46	
Total Paint Including Material		1,166.26
Repair Cost Excludes GST		116,470.44
GST (+7.00%)		8,152.93
Repair Cost Included GST		124,623.37
Deductions (Excludes GST)		
Deduction For Excess	-1,500.00	
Total Of Deductions (Excludes GST)		-1,500.00
Grand Total Excludes GST		114,970.44
GST (+7.00%)		8,047.93
Grand Total Included GST		123,018.37

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/03/2022 15:42 (SGT)
Date of Accident	16/03/2022 17:00 (SGT)
Exact Location of Accident	Bedok South Ave 1, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN2755P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	YU XIAOXIA
Work Permit No	GXXXX856T
Email Address	Lqian2015@hotmail.com
Mobile Phone No	(Phone) +65-91789116
Alternative Phone No	+65-91789116

VEHICLE PARTICULARS

Manufacturer	Porsche
Model	Macan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1984

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00134782102
Cover Note Number	-

DRIVER

Name of Driver	YU XIAOXIA
Work Permit No	GXXXX856T

Date of Birth
Occupation
Type of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

20/11/1976
Indoor
08/03/2012
10 YEARS
Female
(Phone) +65-91789116
+65-91789116
Lqian2015@hotmail.com
772 BEDOK RESERVOIR RD #15-12
-
479251
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Change/cross lane
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
Yes
Yes
Yes
2
No

PASSENGER 1

Name
Gender

NIL
Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Tampines Neighbourhood Police Centre
(Phone) +65-18005871999
(Fax) +65-65871699
6 Tampines Ave 4 Singapore 529682
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT T/20220317/2011.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Reasons for not uploading a video of the accident
Was there any audio recorded?

Yes
Yes
SD CARD WITH TP
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKT6356Z

Manufacturer
Model
Variant
Colour
Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)


Private car

INJURED PERSONS DETAILS

INJURED 1

Name of injured person
Gender
Phone No
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle? SKT6356Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report. T/20220317/2011.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

余曉露
Policyholder's Signature

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.





Motor Private Car

MX1F

R SN

AN0055A

Cov. Type C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1969
Road Transport Act 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO

DMPCSNW00134782102

Engine No.: 015202

Cha No WP1ZZZ96ZKL804520

1. Index Mark and Registration
Number of Vehicle

SMN2755P

2. Name of Policy Holder

YU XIAOXIA

3. Effective date of the Commencement of
Insurance for the purposes of the Regulations
Ordinance or Enactment

31/07/2021
(00:00:00)

Named Drivers Ex Sect 1 \$51,500.00

Additional Ex Other than Named Drivers:

Ex Sect. 1 - Age <= 25 \$53,000.00

Ex Sect. 1 - Age >= 26 \$5500.00

* Age as at date of accident

EX ON WINDSCREEN \$5350.00

4. Date of Expiry of Insurance

30/07/2022

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6. Limitations as to use.*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first \$5500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year

HIRE PURCHASE CO: UNITED OVERSEAS BANK LIMITED AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: COWELL INSURANCE (AGENCY) PTE LTD
Authorised Officer

杨西美

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208364L)
3 Anson Road #16-00 Springleaf Tower Singapore 079909

☎ 6389 6111

☎ 6222 1033

🌐 www.sg.cntaiping.com





**SINGAPORE
POLICE FORCE**



T/20220317/2011

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20220317/2011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:
G / SGT 3 ZHANG LINHAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
17/03/2022 10:39

Officer In Charge Of Case:
TP / GIT /
Other NG BEIFENG
Contact No.: 65476845

Classification Of Case:

NP168



SINGAPORE POLICE FORCE



T/20220317/2011

Police Station Of Origin:
Tampines N.P.O
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20220317/2011

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YU XIAOXIA	ID No.	G1080856T
Related Vehicle	SMN2755P (Car)	Contact No.	91789116
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3C Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	ZHOU YUZH	ID No.	G1774039W
Related Vehicle	SMN2755P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/03/2022 at about 1700hrs, I was driving my car (SMN2755P) along Bedok South Road towards Upper Changi Road on the right most lane with a 4 year old child on board. Weather was clear and road surface was dry.

While I was driving, a car (SKT6356Z) swerved into my lane from the left. I immediately braked and turned my steering wheel to the right wanting to avoid collision. However, my car still collided with the car and mounted onto the curb. I am unsure if any other vehicles were involved in the accident.

Both Ambulance and Traffic Police attended to us. The other party was conveyed by ambulance. My car is installed with camera and memory card was handed over to Traffic Police at scene.

Both my passenger and myself are not injured as of now.



SINGAPORE POLICE FORCE



T/20220317/2011

of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20220317/2011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/03/2022 10:39		Vide Report No.: G/20220316/0170	Station Diary No.: 18
Informant's Particulars			
Name of Informant: YU XIAOXIA		Address: 772 BEDOK RESERVOIR ROAD #15-12 SINGAPORE 479251	
ID Type / ID No.: FIN/NO / G1080856T		Contact No.: Home/Office: Mobile: 91789116	
Nationality: CHINESE		Email: lqian2015@hotmail.com	
Sex: Female	Age: 45	Date of Birth: 20/11/1976	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: Chief operating officer/General Manager		Driving Licence Information: Class: 3C Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/03/2022 17:00	Type of Location: Straight Road
Location: BEDOK SOUTH ROAD				

Weather: Clear	Road Surface: Dry	Road Speed Limit:
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKT6356Z	Car					0
SMN2755P	Car	PORSCHE	MACAN II PDK E6	Grey		1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMN2755P	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSNW001347 82102	31/07/2021	30/07/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Foreign Identification Number

856T

SMN2755P

Yes

19 Mar 2022

PORSCHE

MACAN II PDK E6

Grey

2018

015202

WP1ZZZ95ZKLB04529

185.0 kW (248 bhp)

\$77,668.00

31 Jul 2019

31 Jul 2019

0

\$111,803.00

Yes

30 Jul 2029

\$83,852.00

30 Jul 2029

B - Car above 1600cc or 97kW (130bhp)

10

\$34,000.00

\$25,033.00

\$108,885.00

The information contained herein is correct as at 19 Mar 2022

OK

Porsche Macan 2.0A PDK

- [Overview](#)
- [Financial](#)
- [Accessories](#)
- [Similar](#)
- [Research](#)
- [Photos](#)
- [Map](#)

Price	\$260,888		
Depreciation 	\$30,480 /yr	Reg Date	16-May-2019
	View models with similar depre		(7yrs 1mth 14days COE left)
Mileage	43,500 km (15.1k /yr)	Manufactured 	2018
Road Tax 	\$1,194 /yr	Transmission	Auto
Dereg Value 	\$99,577 as of today (change)	OMV 	\$63,964
COE 	\$48,010	ARF 	\$87,136
Engine Cap	1,984 cc	Power	185.0 kW (248 bhp)
Curb Weight 	1,795 kg	No. of Owners 	2
Type of Vehicle	SUV		