



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

1. GENERAL INFORMATION		
INCIDENT NO.: /20220319/0623	LOCATION OF FIRE:	
FIRE REPORTED ON: 19 March 2022	Along Ayer Rajah Expressway (AYE) (Towards Tuas)	
TIME OF CALL: 12:29:32 hrs	Near Exit 15A	
STATION	Singapore	
COVERAGE: Jurong Fire Station		
2. INCIDENT INFORMATION		
FIRE INVOLVED: The engine compartment of a Dulevo vehicle (YN5916E).		
METHOD OF EXTINGUISHMENT: By SCDF using four dry powder fire extinguishers and three hose reel jets from fire appliances.		
PROBABLE CAUSE OF FIRE: Accidental (Overheating / or electrical origin at the engine compartment)		
DAMAGE OBSERVED*: As a result of the fire, the engine compartment and the cabin of the vehicle were damaged. Other parts of the vehicle sustained heat, smoke and water damage.		
3. FATALITY/INJURY INFORMATION		
NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL
<b>REPORT ISSUED BY:</b> HUANG WEI KANG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

*\*This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

*This is a computer generated report. No signature is required.*