



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TAN JUN HONG			Ref: CS/ASM22002937/Gvy3e2 Date: 08/06/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 899Z	Veh. Inspected	BICYCLE
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M03W3N	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	30/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	CANYON SPEEDMAX CF	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	R4119T19C0078	Colour	BLACK
	Odometer	-	Steering	JAMMED
	Brakes	JAMMED	Modification	NIL
	General	POOR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			1 mm
	L/H Front Tyre			mm
	R/H Rear Tyre			1 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE BICYCLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/03/2022	Inspection Date	05/04/2022
	Survey held at	THE BIKE SETTLEMENT PTE LTD BLOCK 261 WATERLOO STREET #01-06 WATERLOO CENTRE, SINGAPORE 180261		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	