$51\,UBI\,AVE\,1,\#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK,SINGAPORE\,408933\,TEL:(065)\,62563561\,FAX:(065)\,62564315$ 

## **Immediate Advice**

To: AXA Insurance Pte Ltd DATE: 18/4/2022

## Survey details

| Date of loss        | 25/3/2022     |
|---------------------|---------------|
| Date of appointment | 30/3/2022     |
| Date of survey      | 7/4/2022      |
| Location of survey  | YAP LEE MOTOR |
|                     |               |

#### **Vehicle Details:**

| Claim Type:          | THIRD PARTY |
|----------------------|-------------|
| Vehicle number       | GQ 3811J    |
| Make and Model       | TOYOTA DYNA |
| Date of registration | 9/12/2014   |
| Excess               |             |
| Market Value         | \$33,000.00 |
| Parf Rebate          | \$10,673.00 |
| Nett Loss            | \$22,327.00 |

## Repair details

| al Estimate |
|-------------|
|-------------|

## Proposed/Revised repair cost:

| Parts                    |  |
|--------------------------|--|
| "Check items (Estimated) |  |
| Labour                   |  |
| Total                    |  |
| Lump Sum (Estimated)     |  |
| ,                        |  |

# Number of days of repair 6 days (est)

#### Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$4,000.00-\$5,000.00