



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Lumens Auto Pte Ltd 22 Sin Ming Lane #01-74 Midview City Singapore 573969 Mobile: 83221830				
		Document No. 0					
		Document Date 28/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW50R	AHXEBW Q8	28/07/2021	SNB0207U	0	14138	66TP/SNB0207U/280321
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU003091932		2ZR2G92623	60	Shashitharan	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SFW5977G ACC DATE:25/03/202 2TOW IN:16:00HRS 28/03/22 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR				180.00	
3	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00	
4	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				2160.00	
5	B	BP-RES2 RESRPAY ACC AFF AREA				1770.00	
6	1	U52023-47030 REINFORCEMENT	1.00	353.10		353.10	
7	2	U52576-47060 RETAINER, RR BUMPER	1.00	140.50		140.50	
8	3	U52159-47927 COVER, RR BUMPER	1.00	515.10		515.10	
9	4	U52169-47070 COVER, RR BUMPER,	1.00	23.40		23.40	
10	5	S52161-0K040 PIECE,RR BUMPER	10.00	4.30		43.00	
11	6	U52453-47900 GUARD, RR BUMPER,	1.00	396.90		396.90	
12	7	U52592-47080 SEAL, RR BUMPER	1.00	125.40		125.40	
13	8	U81920-47030 REFLECTOR ASSY,	1.00	41.40		41.40	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		6,028.80		
			Labour		GST 7.00%		
			Sublet		422.02		
			Lubrication/Fluid		Less		
			Others		0.00		
				Amount Due		6,450.82	

Customer Copy